



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

January 12, 2023

Ms. Christal Kerr
Adventurer LP
3303 w washington ave
Yakima, WA 98903

NEF-107KL
23E-001

Subject: Propane Leak May Cause Fire

Dear Ms. Kerr:

This letter serves to acknowledge Adventurer LP's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ADVENTURER/ADVENTURER TRUCK CAMPER/9999

Mfr's Report Date: January 4, 2023

NHTSA Campaign Number: 23E-001

Components:

EQUIPMENT:RECREATIONAL VEHICLE/TRAILER:LPG SYSTEMS

Potential Number of Units Affected: 263

Problem Description:

Adventurer LP (Adventurer) is recalling certain 2021-2022 Adventurer 19RD, 23RB, and 24DS truck bed campers. The service valves on the LPG tanks may have improper thread depth, which can cause a propane leak.

Consequence:

A propane leak in the presence of an ignition source can increase the risk of a fire.

Remedy:

Dealers will inspect and if necessary, replace the service valves, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Adventurer customer service at 1-509-895-7064.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no



later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Please ensure the following requirements are met:

The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

AMENDED 573 REQUIRED.

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims. Please include the date when Adventurer LP decided to file a recall.

AMENDED 573 REQUIRED.

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

AMENDED 573 REQUIRED.

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (§ 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

AMENDED 573 REQUIRED.

Adventurer LP's contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement