



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

March 3, 2023

Mr. Steve Thorne  
National Warranty Manager  
Airstream, Inc.  
419 W Pike St.  
Jackson Center, OH 45365

NEF-107KL  
23V-134

**Subject:** Gas Valves May Fracture Causing Gas Leak

Dear Mr. Thorne:

This letter serves to acknowledge Airstream, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

AIRSTREAM/ATLAS/2021-2023  
AIRSTREAM/BAMBI/2021-2023  
AIRSTREAM/BASECAMP/2021-2023  
AIRSTREAM/INTERSTATE/2021-2023

**Mfr's Report Date:** March 1, 2023

**NHTSA Campaign Number:** 23V-134

**Components:**

EQUIPMENT:APPLIANCE:OVEN/STOVE/COOKTOP

**Potential Number of Units Affected:** 6,827

**Problem Description:**

Airstream Inc. (Airstream) is recalling certain 2021-2023 Basecamp, Bambi, Atlas, and Interstate travel trailers, equipped with certain SDS2 2-Burner Drop-in Cooktops. The internal aluminum burner tubes that connect to the gas valves may fracture and cause a gas leak.

**Consequence:**

A gas leak in the presence of an ignition source can increase the risk of a fire.

**Remedy:**

Dealers will install a regulator support bracket, free of charge. Owner notification letters are expected to be mailed April 29, 2023. Owners may contact Airstream Customer Service at 877-596-6111 (Travel Trailer ext. 7491) or (Touring Coach ext. 7401).

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Airstream, Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at [kristin.lepper@dot.gov](mailto:kristin.lepper@dot.gov). We look forward to working with you.

Sincerely,



Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement