



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

June 9, 2023

Mr. Todd Miorin  
Senior Director - Product Safety  
Pierce Manufacturing  
1917 Four Wheel Drive  
Oshkosh, WI 54902

NEF-107MR  
23V-407

**Subject:** Stabilizer Beams May Develop Cracks

Dear Mr. Miorin:

This letter serves to acknowledge Pierce Manufacturing's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

PIERCE/LADDER AND PLATFORM/2016-2022

**Mfr's Report Date:** June 6, 2023

**NHTSA Campaign Number:** 23V-407

**Components:**

STRUCTURE

**Potential Number of Units Affected:** 5

**Problem Description:**

Pierce Manufacturing (Pierce) is recalling certain 2016-2022 Ascendant 107' Aerials and 110' Platforms mounted on single rear axle Enforcer chassis. The galvanized stabilizer beams may develop cracks.

**Consequence:**

Cracks can cause instability when an aerial ladder or platform is elevated, increasing the risk of injury.

**Remedy:**

Dealers will inspect and replace the galvanized stabilizer beams as necessary, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Pierce customer service at 1-888-974-3723.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

Please ensure the following requirements are met:

The total number of products potentially containing the defect or noncompliance (49 CFR 573.6 (c)(3)).

**AMENDED 573 REQUIRED.**



The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

**AMENDED 573 REQUIRED.**

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

**AMENDED 573 REQUIRED.**

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

**AMENDED 573 REQUIRED.**

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

**AMENDED 573 REQUIRED.**

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Pierce Manufacturing's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink that reads "Alex Ansley". The signature is written in a cursive style with a checkmark at the end.

Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement