



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

November 6, 2023

Mr. Greg Gunther
Department Manager VCA
Mercedes-Benz USA, LLC
13470 International Parkway
Jacksonville, FL 32218

NEF-107ES
23V-733

Subject: Sunroof May Close Unexpectedly/FMVSS 118

Dear Mr. Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES-BENZ/GLS580/2020

Mfr's Report Date: November 1, 2023

NHTSA Campaign Number: 23V-733

Components:

VISIBILITY:SUN/MOON ROOF ASSEMBLY

Potential Number of Units Affected: 8

Problem Description:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2020 GLS580 vehicles. Due to a software error, the sunroof may close unexpectedly when the "car wash mode" is activated. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 118, "Power-operated Window Systems."

Consequence:

A sunroof that closes unexpectedly can increase the risk of injury.

Remedy:

Dealers will update the sunroof control unit software, free of charge. Owner notification letters are expected to be mailed December 31, 2023. Owners may contact MBUSA customer service at 1-800-367-6372.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

Please amend the chronology to clarify the population change from the original filing.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Mercedes-Benz USA, LLC's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement