

**Recall Quarterly Report****23V-150**

**Manufacturer Name :** Terex Advance Mixer, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 23V-150 /  
**Recall Subject :** Steering Shaft May Separate from Steering Column  
**Owner Notification Beginning Date :** MAY 22, 2023  
**Owner Notification End Date:** MAY 22, 2023

**Quarterly Reports**

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	APR 01, 2025	2025-1	271	10	0	0
7	FEB 05, 2025	2024-4	271	10	0	0
6	OCT 01, 2024	2024-3	271	10	0	0
5	JUL 01, 2024	2024-2	271	10	0	0
4	APR 02, 2024	2024-1	271	10	0	0
3	JAN 02, 2024	2023-4	271	10	0	0
2	OCT 02, 2023	2023-3	271	10	0	0
1	OCT 02, 2023	2023-2	271	10	0	0

This Document Last Updated : APR 01, 2025

**Definitions :**

**Reporting Period:** The reporting period is the manufacturer is reporting recall completion figures.

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.