

**Recall Quarterly Report****23V-392**

**Manufacturer Name :** Subaru of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 23V-392 /WRJ-23  
**Recall Subject :** Ball Joint May Separate from Lower Control Arm  
**Owner Notification Beginning Date :** JUN 27, 2023  
**Owner Notification End Date:** JUN 27, 2023



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 19, 2024	2023-4	5	5	0	0
2	OCT 23, 2023	2023-3	5	5	0	0
1	JUL 24, 2023	2023-2	5	4	0	0

This Document Last Updated : JAN 24, 2024

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.