

Recall Quarterly Report**23V-392**

Manufacturer Name : Subaru of America, Inc.
NHTSA Recall No. / MFR Recall No. : 23V-392 /WRJ-23
Recall Subject : Ball Joint May Separate from Lower Control Arm
Owner Notification Beginning Date : JUN 27, 2023
Owner Notification End Date: JUN 27, 2023



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	APR 18, 2024	2024-1	5	5	0	0
3	JAN 19, 2024	2023-4	5	5	0	0
2	OCT 23, 2023	2023-3	5	5	0	0
1	JUL 24, 2023	2023-2	5	4	0	0

This Document Last Updated : APR 24, 2024

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.