

Part 573 Safety Recall Report

23V-103

Manufacturer Name : Aluminum Trailer Company (ATC)

Submission Date : APR 14, 2023

NHTSA Recall No. : 23V-103

Manufacturer Recall No. : 23E-002



Manufacturer Information :

Manufacturer Name : Aluminum Trailer Company (ATC)

Address : 751 N Tomahawk Trail

Nappanee IN 46650

Company phone : 574-773-2440

Population :

Number of potentially involved : 757

Estimated percentage with defect : 11 %

Vehicle Information :

Vehicle 1 : 2021-2023 ATC Toyhauler and Quest Trailers

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : In conjunction with recall issued by Suburban Manufacturing (22E-002), All SDS2 two burner cooktops issued to ATC during the established timeline of 1/16/18 through 1/11/23. 757 ATC toyhaulers and quest trailers that were built during that time period that use the Suburban SDS2 2 burner drop in cooktop question are impacted

Production Dates : DEC 16, 2020 - JAN 31, 2023

VIN Range 1 : Begin : 5JX1C2425MD221925 **End :** 5JX1U2428PE230663

☒ Not sequential

Description of Defect :

Description of the Defect : Suburban Mfg has advised on Recall 23E-002 that certian vehicles equipped with SDS2- 2 burner drop in cooktops that were supplied during the period of 1/16/18 to 1/11/23 may have a burner tube that could crack resulting in a propane leak.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The internal aluminum burner tube connected the gas valve may fracture from excessive vibration or shock and may crack resulting in a gas leak when the gas valve is opened to use the appliance. The resulting gas may result in a fire and/or explosion which could result in personal injury

Description of the Cause : The internal aluminum burner tube that connects the gas valves to the cooktop burners may fracture from excessive vibration or shock experienced through travel.

Identification of Any Warning that can Occur : The owner could possibly head a louder than nornma hissing sound or small propane odor when the cooktop gas valve is the in the on position.

Involved Components :

Component Name 1 : SDS2- 2 Burner Drop In Cooktop
Component Description : 2 burner drop in cooktop
Component Part Number : 0017890

Supplier Identification :

Component Manufacturer

Name : Suburban Manufacturing Co
Address : 676 Broadway
Dayton Tennessee 37321
Country : United States

Chronology :

Suburban Mfg notified of recall 22E-002. After review of the time period provided in the recall, it was determined that 757 toyhauler and quest trailers are potentially impacted by the recall. ATC determined the recall population and confirmed receipt of the impacted product on 2/21/23 and filed the claim.

Description of Remedy :

Description of Remedy Program : ATC will supply replacement materials if needed as they will be supplied by Suburban under the recall. ATC will supply the parts kit needed to make the repairs. Repair time of 0.25 hours will be allotted for the repair. Parts will be sent out within 2 weeks of the repair request. If a customer or dealer have incurred costs for the cooktop that would have been covered with this repair, those costs will be reimbursed.

How Remedy Component Differs from Recalled Component : The repair kit consists of a support bracket with tape, screws, loctite and a decal identifier for the remedy of the stock number for future identification.

Identify How/When Recall Condition was Corrected in Production : Suburban corrected this issue on all new production/inventory as of 1/12/23 per notification received.

Recall Schedule :

Description of Recall Schedule : Recall notification will begin on 4/17/23 and be completed by 4/21/23. Owners will be notified via first class mail. Dealers will be notified via email with return receipts

Planned Dealer Notification Date : APR 17, 2023 - APR 21, 2023

Planned Owner Notification Date : APR 17, 2023 - APR 21, 2023

* NR - Not Reported