

# Part 573 Safety Recall Report

# 23V-103

**Manufacturer Name :** Aluminum Trailer Company (ATC)**Submission Date :** FEB 21, 2023**NHTSA Recall No. :** 23V-103**Manufacturer Recall No. :** 23E-002**Manufacturer Information :**

Manufacturer Name : Aluminum Trailer Company (ATC)

Address : 751 N Tomahawk Trail

Nappanee IN 46650

Company phone : 574-773-2440

**Population :**

Number of potentially involved : 757

Estimated percentage with defect : 11 %

**Vehicle Information :**

Vehicle 1 : 2021-2023 ATC Toyhauler and Quest Trailers

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

**Descriptive Information :** In conjunction with recall issued by Suburban Manufacturing (22E-002), All SDS2 two burner cooktops issued to ATC during the established timeline of 1/16/18 through 1/11/23. 757 ATC toyhaulers and quest trailers that were built during that time period that use the Suburban SDS2 2 burner drop in cooktop question are impacted

Production Dates : DEC 16, 2020 - JAN 31, 2023

VIN Range 1 : Begin : 5JX1C2425MD221925 End : 5JX1U2428PE230663

 Not sequential**Description of Defect :**

**Description of the Defect :** Suburban Mfg has advised on Recall 23E-002 that certian vehicles equipped with SDS2- 2 burner drop in cooktops that were supplied during the period of 1/16/18 to 1/11/23 may have a burner tube that could crack resulting in a propane leak.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** The internal aluminum burner tube connected the gas valve may fracture from excessive vibration or shock and may crack resulting in a gas leak when the gas valve is opened to use the appliance. The resulting gas may result in a fire and/or explosion which could result in personal injury

**Description of the Cause :** The internal aluminum burner tube that connects the gas valves to the cooktop burners may fracture from excessive vibration or shock experienced through travel.

**Identification of Any Warning that can Occur :** The owner could possibly hear a louder than normal hissing sound or smell propane odor when the cooktop gas valve is in the on position.

## Involved Components :

**Component Name 1 :** SDS2- 2 Burner Drop In Cooktop

**Component Description :** 2 burner drop in cooktop

**Component Part Number :** 0017890

## Supplier Identification :

### Component Manufacturer

**Name :** Suburban Manufacturing Co

**Address :** 676 Broadway

Dayton Tennessee 37321

**Country :** United States

## Chronology :

Suburban Mfg notified of recall 22E-002. After review of the time period provided in the recall, it was determined that 757 toyhauler and quest trailers are potentially impacted by the recall.

## Description of Remedy :

**Description of Remedy Program :** TBD - Awaiting repair instructions and plan for reimbursement from Suburban.

**How Remedy Component Differs from Recalled Component :** NR

**Identify How/When Recall Condition was Corrected in Production :** NR

## Recall Schedule :

**Description of Recall Schedule :** Recall notification will begin on 4/17/23 and be completed by 4/21/23.

Owners will be notified via first class mail. Dealers will be notified via email with return receipts

Planned Dealer Notification Date : APR 17, 2023 - APR 21, 2023

Planned Owner Notification Date : APR 17, 2023 - APR 21, 2023

\* NR - Not Reported