OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-157

Manufacturer Name: Eveland's Inc.

Submission Date: MAR 30, 2023

NHTSA Recall No.: 23V-157



Manufacturer Information:

Manufacturer Recall No.: NR

Manufacturer Name: Eveland's Inc.

Address: 507 State 371 NW

Backus MN 56435

Company phone: 218-947-4932

Population:

Number of potentially involved: 25 Estimated percentage with defect: NR

Vehicle Information:

Vehicle 1: 2022-2022 Scamp Trailer 13ft

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The supplier Dometic Corp indicated that the scope date(s) are from August 2020,

through June 2021.

Production Dates: NOV 02, 2021 - MAY 31, 2022

Description of Defect:

Description of the Defect: Per Dometic Recall 22E021; "The burner control valve, mated directly to the

control knob via the valve stem, on the cooktop may leak gas."

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Per Dometic Recall 22E021, "There is an increased risk of fire and injury. The

detailed description of the potential safety-related defect is associated with the burner control valve where the valve stem is located directly behind the cooking knob of the cooktops. There is a potential for the gas leak behind the control knob to ignite and create a small pilot flame and present a possibility

of a burn to the user.

Description of the Cause: NR
Identification of Any Warning NR
that can Occur:

Involved Components:

Component Name 1: Dometic

Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR Country: NR

Chronology:

NR

Description of Remedy:

Description of Remedy Program : NR

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR was Corrected in Production :

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

^{*} NR - Not Reported