

# Part 573 Safety Recall Report

## 23V-197

**Manufacturer Name :** Shadow Trailer, LLC**Submission Date :** MAR 28, 2023**NHTSA Recall No. :** 23V-197**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Shadow Trailer, LLC

Address : 951 SW 21st Place

Williston FL 32696

Company phone : 352-529-2190

**Population :**

Number of potentially involved : 270

Estimated percentage with defect : 16 %

**Vehicle Information :**

Vehicle 1 : 2016-2023 Shadow Trailer Living Quarter

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Suburban Manufacturing identified glass top stoves with a defective component. 270 units at this time. Models affected: 7'6"LQ/9'LQ/9'6"LQ/10'6"LQ/12'6"LQ/14'LQ

Production Dates : JAN 02, 2016 - MAR 24, 2023

VIN Range 1 : Begin : 1S9GS2929GW873074 End : 1S9GH2326PW873010 ☒ Not sequential**Description of Defect :**

Description of the Defect : The internal aluminum burner on the SDS2 glass top stove may fracture due to excessive vibration.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : LP leak when burner is on.

Description of the Cause : NR

Identification of Any Warning : If ignited, could cause fire/explosion.  
that can Occur :**Involved Components :**

Component Name 1 : 2 burner cooktop

Component Description : LP stove

Component Part Number : SDS2

Supplier Identification :

Component Manufacturer

Name : Suburban Manufacturing

Address : 676 Broadway Street  
Dayton Tennessee 37321

Country : United States

Chronology :

Issue identified by Suburban Manufacturing. Recall campaign letter received late February timeframe but no "repair/resolution" given at that time. Late February/early March, Shadow collects data from Production Build Reports and Warranty Registration portal and compiles list of selling dealers and end users and quarantines all stoves in our inventory pending repair/replacement instructions from Suburban. Shadow halts all shipments of products with stove in campaign installed., Total units based on data collected is 270, however, there are some units that offer a stove "delete" option but we cannot identify all units so we assume that all 270 have a stove installed. March 3-10 Shadow sends out mail/email/phone calls to dealers with list of units sold during the timeframe listed in the campaign letter, a copy of the campaign letter with a cover letter to halt sales of any trailer with a stove installed. This same week, Customer/End user mail/email/phone calls begin with a cover letter/campaign letter and instructions. To date we have not had any warranty claims related to this campaign or stove operation issues

Description of Remedy :

Description of Remedy Program : A repair kit is sent to OEM, Dealers and authorized repair centers. See uploaded document titled-206286 SDS2 FIELD RECALL REMEDY INSTRUCTION SHEET-03-07-23 issued by Suburban Manufacturing and approved by NHTSA.

How Remedy Component Differs from Recalled Component : An additional support bracket for the burner tubes.

Identify How/When Recall Condition was Corrected in Production : All SDS2 stoves quarantined and returned to Suburban. SDS2 stoves were sent back to us with additional support brackets installed.

**Recall Schedule :**

Description of Recall Schedule : Dealers notified on 03/10/23 through 03/17/23. Owners notified 03/10/23 through 03/24/23

Planned Dealer Notification Date : MAR 28, 2023 - MAR 28, 2023

Planned Owner Notification Date : MAR 28, 2023 - MAR 28, 2023

\* NR - Not Reported