

# Part 573 Safety Recall Report

# 23V-408

**Manufacturer Name :** Imagine Fiberglass Products Inc.

**Submission Date :** JUL 08, 2024

**NHTSA Recall No. :** 23V-408

**Manufacturer Recall No. :** 2023-01



## Manufacturer Information :

## Population :

**Manufacturer Name :** Imagine Fiberglass Products Inc.

**Number of potentially involved :** 25

**Address :** 560 Weber St North

**Estimated percentage with defect :** 100 %

Waterloo 00 N2L 5C6

**Company phone :** 8048751

## Vehicle Information :

**Vehicle 1 :** 2021-2023 Trillium Heritage 1300/4500

**Vehicle Type :** TRAILERS

**Body Style :** OTHER

**Power Train :** NR

**Descriptive Information :** Campers with the Suburban SDS2 2-Burner Cooktop, Stock # 3032AST

**Production Dates :** JAN 04, 2021 - MAY 15, 2023

**VIN Range 1 : Begin :** 2F9BC13SONA105011 **End :** 2F9LT15S7NA105007  Not sequential

**Vehicle 2 :** 2021-2023 L'Air Lion 1300/4500

**Vehicle Type :** TRAILERS

**Body Style :**

**Power Train :** NR

**Descriptive Information :** L'Air Lion is a larger trailer. The same issue exists with some trailers which have the Suburban cooktop installed.

**Production Dates :** JAN 04, 2021 - MAY 15, 2023

**VIN Range 1 : Begin :** 2F9LT15C9NA105003 **End :** 2F9BC13S2PA105045  Not sequential

## Description of Defect :

**Description of the Defect :** On L'Air Camper 1300 and 4500 RVs produced between 2021 through 2023 and equipped with a Suburban SDS2 cooktop, the aluminum tubes that connect the gas valves to the cooktop burners could crack. If this happens, the tubes could leak propane when the top burner gas valve is opened to use the appliance.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

Description of the Safety Risk : A propane gas leak could create the risk of a fire or explosion if ignited which, could result in personal injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

## Involved Components :

Component Name 1 : Suburban SDS

Component Description : 2 burner cooktop

Component Part Number : 3032AST

## Supplier Identification :

### Component Manufacturer

Name : Suburban Manufacturing Co

Address : 676 Broadway St  
Dayton Texas 37321

Country : United States

## Chronology :

We were notified by our supplier of the Suburban cooktop on May 1, 2023.

## Description of Remedy :

Description of Remedy Program : We are working with Suburban and our distributor, GLP Canada, to provide customers with repair options most convenient for them. Local customers may choose to bring their L'Air Camper to our L'Air Camper manufacturing facility in Waterloo for us to conduct the repair. Customers for whom this is not a viable option may bring their L'Air Camper to any authorized RV repair centre in Canada or the US. Please note: it is imperative that the repair be executed by an authorized RV service technician. With proper documentation, Suburban will reimburse owners for the retail cost of an SDS2 cooktop if it was replaced prior to the issuing of this recall.

**How Remedy Component Differs from Recalled Component :** Suburban Manufacturing has provided a field recall kit with a bracket assembly to correct the issue.

**Identify How/When Recall Condition was Corrected in Production :** Campers which have been delivered will be fixed using the field kit as per above. Campers still in production will be furnished with an SDS 2 stock # 3033 AST.

### Recall Schedule :

**Description of Recall Schedule :** Identify which campers require retrofit.  
Identify which customers have taken delivery and prepare notification letters accordingly.

**Planned Dealer Notification Date :** JUN 06, 2023 - JUN 28, 2023

**Planned Owner Notification Date :** JUN 06, 2023 - JUN 28, 2023

\* NR - Not Reported