

# Part 573 Safety Recall Report

# 23V-528

**Manufacturer Name :** Midway Specialty Vehicles

**Submission Date :** JUL 28, 2023

**NHTSA Recall No. :** 23V-528

**Manufacturer Recall No. :** NR



## Manufacturer Information :

**Manufacturer Name :** Midway Specialty Vehicles

**Address :** 2940 Dexter Drive

Elkhart IN 46514

**Company phone :** 574-264-2530

## Population :

**Number of potentially involved :** 4

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2022-2022 FORD TRANSIT

**Vehicle Type :** LIGHT VEHICLES

**Body Style :** VAN

**Power Train :** GAS

**Descriptive Information :** Cummins provided a list of affected generator serial numbers purchased by Midway and our Regulatory Compliance Team determined the scope from our production records.

**Production Dates :** MAR 22, 2022 - OCT 27, 2022

**VIN Range 1 : Begin :** 1FTBR3X86NKA36881 **End :** 1FTBW3U85NKA85308  **Not sequential**

## Description of Defect :

**Description of the Defect :** The fuel hose between the inline fuel filter and the Injection Pump Module (IPM) may have inadequate clamp force, possibly resulting in a gasoline leak.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** A gasoline leak in the presence of an ignition source may increase the risk of fire

**Description of the Cause :** The cause of the issue is an inadequate specification of the fuel hose.

**Identification of Any Warning that can Occur :** Bystanders may see or smell gasoline.

## Involved Components :

Component Name 1 : HOSE, FUEL

Component Description : Gasoline fuel hose between the IPM and fuel filter

Component Part Number : A064P026

## Supplier Identification :

### Component Manufacturer

Name : CUMMINS INC

Address : 301 WASHINGTON ST  
COLUMBUS Indiana 47202

Country : United States

## Chronology :

4/13/2023 Cummins notified Midway Compliance by email of their Onan generator recall.

## Description of Remedy :

Description of Remedy Program : The remedy consists of inspection and replacement of the fuel hose and clamp.

How Remedy Component Differs from Recalled Component : The remedy fuel hose has a unique part number A073T925.

Identify How/When Recall Condition was Corrected in Production : The recall condition was corrected in production at Cummins in February 2023.

## Recall Schedule :

Description of Recall Schedule : CUMMINS WILL NOTIFY DEALERS & AFFECTED RETAIL OWNERS

Planned Dealer Notification Date : JUL 28, 2023 - JUL 28, 2023

Planned Owner Notification Date : JUL 28, 2023 - JUL 28, 2023

\* NR - Not Reported