The information contained in this report was submitted pursuant to 49 CFR §573

Manufacturer Name : Forest River, Inc.

Submission Date : OCT 04, 2023

NHTSA Recall No.: 23V-660

Manufacturer Recall No.: 110-1686

Manufacturer Information :

Manufacturer Name : Forest River, Inc. Address : 55470 CR 1 P.O. Box 3030 Elkhart IN 46515-3030 Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1:	2024-2024 Forest River Inc. Coachmen Brookstone Fifth Wheels	
Vehicle Type :	TRAILERS	
Body Style :	OTHER	
Power Train :	NR	
Descriptive Information :	The scope was determined using manufacturing records of when plant ran out of 15AMP 12V fuses. 2024 BROOKSTONE BKF344FL 1 2024 BROOKSTONE BKF352RLD 1 2024 BROOKSTONE BKF374RK 1 Grand Total 3	the manufacturing
Production Dates :	AUG 22, 2023 - SEP 26, 2023	
VIN Range 1:		Not sequential
Vehicle Type : Body Style : Power Train : Descriptive Information :	OTHER	the manufacturing
Production Dates :	AUG 22, 2023 - SEP 26, 2023	
VIN Range 1:		☐ Not sequential
		L



Number of potentially involved :

Estimated percentage with defect : 100 %

Population :

50

23V-660

Part 573 Safety Recall Report

23V-660

Page 2

Vehicle Type : Body Style : Power Train :	OTHER NR	-	
Descriptive Information :	The scope was determined plant ran out of 15AMP 12V 2024 CHAPARRAL LITE 2024 CHAPARRAL LITE 2024 CHAPARRAL LITE 2024 CHAPARRAL LITE 2024 CHAPARRAL LITE 2024 CHAPARRAL LITE Grand Total 21	fuses. CLF235RK 3 CLF274BH 4 CLF284RL 4 CLF30BHS 3	ng records of when the manufacturing 3 4 4 3 7
Production Dates :	AUG 22, 2023 - SEP 26, 202	3	
VIN Range 1:	Begin : NR	End: NR	□ Not sequential
Descriptive intormation.	plant ran out of 15AMP 12V	e	g records of when the manufacturing
	2024 SHASTA PHOENIX 2024 SHASTA PHOENIX Grand Total 19	SPF235RK 2 SPF25RE 2 SPF30BH 1 SPF30RLS 1 SPF334FL 2 SPF360BH 1	2 1 1 2 1 4
Production Dates : VIN Range 1 :	2024 SHASTA PHOENIX 2024 SHASTA PHOENIX Grand Total 19 AUG 22, 2023 - SEP 26, 202	SPF235RK2SPF25RE2SPF30BH1SPF30RLS1SPF334FL2SPF360BH1SPF370BAF4SPF373MBRB6	2 1 1 2 1 4
	2024 SHASTA PHOENIX 2024 SHASTA PHOENIX Grand Total 19 AUG 22, 2023 - SEP 26, 202	SPF235RK 2 SPF25RE 2 SPF30BH 1 SPF30RLS 1 SPF334FL 2 SPF360BH 1 SPF370BAF 4 SPF373MBRB 6	2 1 2 1 4 3
VIN Range 1 : escription of Defect :	2024 SHASTA PHOENIX 2024 SHASTA PHOENIX Grand Total 19 AUG 22, 2023 - SEP 26, 202 Begin : NR	SPF235RK 2 SPF25RE 2 SPF30BH 1 SPF30RLS 1 SPF334FL 2 SPF360BH 1 SPF370BAF 4 SPF373MBRB 6 3 End : NR	2 1 2 1 4 3
VIN Range 1 : escription of Defect : Description of the Defe	2024 SHASTA PHOENIX 2024 SHASTA PHOENIX Grand Total 19 AUG 22, 2023 - SEP 26, 202 Begin : NR	SPF235RK 2 SPF25RE 2 SPF30BH 1 SPF30RLS 1 SPF334FL 2 SPF360BH 1 SPF370BAF 4 SPF373MBRB 6 3 End : NR	2 1 2 1 4 3 T units in the manufacturing plants' ng dates, it was discovered that a

Part 573 Safety Recall Report	
-------------------------------	--

	The fuse may not fail under certain conditions as intended, leading to the circuits to potentially cause a fire which may lead to property damage. The manufacturing plant had a shortage of the appropriate size of fuse.			
Identification of Any Warning that can Occur :				
nvolved Components :				
Component Name 1: 3	BOAMP Fuse, 12V			
Component Description : 3	BOAMP Fuse, 12V			
Component Part Number : N	J/A			
Supplier Identification :				
Component Manufacturer				
Name : NR				
Address : NR				

Country: NR

Chronology :

On September 27, 2023, during a routine Corporate Standards Audit of units in the ship yard with certain August manufacturing date, was discovered that a possible incorrect fuse may have been installed into the vehicles power distribution center.

On September 28, 2023, the Corporate Standards Manager and manufacturing plant contacted Forest River's Office of Corporate Compliance ("OCC") the same day. OCC opened a research item.

On September 29, 2023, Forest Rivers Corporate Recall Committee voted to recall. All vehicles are located at Dealers, therefore there will not be an owner notification for this recall.

On October 3, 2023, during our recall notification process to Dealers, it was found that 3 units were retail sold. Therefore, we will be sending owner notification letters.

The information contained in this report was submitted pursuant to 49 CFR §573

[
Description of Remedy :	
Description of Remedy Program :	Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to remove the current 30 AMP 12V fuse and replace it with a 15 AMP 12V fuse.
	What is the Forest River Customer Service Phone Number? (574) 825-7101
	If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:
	Coachmen Fifth Wheels Forest River, Inc. Attn: WARRANTY MANAGER PO Box 30 Middlebury, IN 46540
	Affected Component - 30AMP Fuse, 12V Replacement Component - 15AMP Fuse, 12V The fuse will now be the correct amperage.
	The week of August 23, 2023, the manufacturing plant received their shipment of 15AMP fuses. Unknown to plant management that certain personnel had installed 30AMP fuses where 15AMP fuses were required.
Recall Schedule :	
Description of Recall Schedule :	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.
Planned Dealer Notification Date : Planned Owner Notification Date :	

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573