

Part 573 Safety Recall Report

23V-895

Manufacturer Name : Daimler Trucks North America, LLC**Submission Date :** MAR 18, 2024**NHTSA Recall No. :** 23V-895**Manufacturer Recall No. :** FL991**Manufacturer Information :**

Manufacturer Name : Daimler Trucks North America, LLC

Address : 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone : 800-745-8000

Population :

Number of potentially involved : 2,547

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2024-2024 FREIGHTLINER M2 BUSINESS CLASS

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : 2-DOOR

Power Train : DIESEL

Descriptive Information : Vehicles in the production range built with a transmission that does not contain a park pawl at the Mt Holly plant.

Production Dates : APR 03, 2023 - OCT 12, 2023

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Certain Freightliner M2 Business Class 2024 vehicles with a transmission that does not possess a park pawl were built with an incorrect transmission shifter that contains a park position (PRNDL).

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : On the affected vehicles, the driver may place the shift lever into the park position and mistakenly believe the vehicle is safely parked with the park pawl in place and may forget to set the park brake, leaving the vehicle in neutral and unattended. This may result in a vehicle rollaway which can increase the risk of a crash.

Description of the Cause : Incorrect part install at the plant.

Identification of Any Warning that can Occur : No warning or detectability.

Involved Components :

Component Name 1 : Shift Control

Component Description : RNDL

Component Part Number : 07-25539-000

Component Name 2 : Shift Control

Component Description : RNDL

Component Part Number : 07-24504-000

Supplier Identification :

Component Manufacturer

Name : Daimler Truck North America

Address : 4747 N. Channel Ave.

Portland Oregon 97217

Country : United States

Chronology :

Refer attached chronology.

Description of Remedy :

Description of Remedy Program : A Daimler Truck North America authorized service facility will inspect the affected vehicles for the presence of the park position on the transmission shift lever. If the transmission shift lever contains a park position, it will be replaced with a new transmission shift lever that does not include a park position. Details of the reimbursement plan will be included in the owner's notification letter. Owners are directed to seek reimbursement through authorized dealers.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : APR 15, 2024 - APR 15, 2024

Planned Owner Notification Date : APR 15, 2024 - APR 15, 2024

* NR - Not Reported