



New Safety Recall Advanced Communication – 89A

FCA US LLC (FCA US) has announced a safety recall on certain Body Control Modules (BCMs) part numbers 68497537AG, 68497538AG, 68628390AC, 68497538AF and 68628390AB intended for use on some 2022 and 2023 Model Year (MP) Jeep® Compass vehicles.

REASON FOR THIS SAFETY RECALL

Some of the above BCMs may contain software which may result in an Instrument Panel Cluster (IPC) backlight with no adjustability. If installed in a vehicle, an IPC display that is not visible to the driver may result in the driver's attention being distracted from the driving task while trying to locate a desired display, which can cause a vehicle crash without prior warning.

Federal Motor Vehicle Safety Standard (FMVSS) 571.101 Controls and displays S5.3.2, Brightness of illumination of controls and indicators, states that controls and indicators "must be adjustable to provide at least two levels of brightness." Vehicles produced with incorrectly programmed BCM software can experience the inability to adjust the brightness on the instrument panel center cluster to provide at least two levels of brightness.

SERVICE ACTION

FCA US will conduct a voluntary safety recall on all affected parts to repurchase suspect BCMs. If installed on a vehicle, FCA US will reprogram the BCM. The remedy for this condition is not currently available. Dealers will be notified of the launch of this safety recall by way of established communication methods. This recall is estimated to launch in 4th Quarter of 2023.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations
FCA US LLC