

Reference Number: GCUS-3-2953

REVISION: N222372310-01 – Safety Recall - Inadequate Fuel Pump Flow

****IMPORTANT PARTS UPDATE****

GLOBAL SAFETY FIELD INVESTIGATIONS

DCS6589

URGENT - DISTRIBUTE IMMEDIATELY

Date: May 25, 2023

Subject: REVISION: N222372310-01 – Safety Recall

Inadequate Fuel Pump Flow

****IMPORTANT PARTS UPDATE****

Models: 2021-2022 Chevrolet Equinox

2022 GMC Terrain

To: All General Motors Dealers

This bulletin is being revised to update the part numbers for the Fuel Pump Module. Please discard all previous copies of bulletin N222372310.

Frequently Asked Questions Document (FAQs)

Attached to this message you will find a document that addresses the ten most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS