

APA4 Recall Campaign – Check connection points on the body and rework if necessary

APA4 Recall Campaign - Check connection points on the body and rework if necessary

ID Number	APA4
Models	911 (992) Taycan (Y1A)
Model Years	2020-2022
VIN List	Attached
Number of Affected VINs	3
Issue Description	Due to a process error in the car body production line, it is possible that certain welding and other particular connection points were not properly completed in some vehicles.
What Dealers Should do	Please arrange for customer vehicles to have the campaign carried out as soon as possible.
What Will Porsche Do?	Vehicles will have the remedy performed once it is available. The remedy is now available as of 6/5/2023.
TI Number	No. 76-23
Customer letter	To be sent at a later date.
Customer Reactive Statement	Our highest priority is the safety of anyone traveling in one of our cars. Through our own testing and quality checks we have identified a potential issue affecting a total of three 911 Carrera and Taycan vehicles sold in the United States. Due to a process error in the car body production line, it is possible that certain welding processes affecting specific parts of the car were not executed to the standard expected on affected vehicles. No incidents or complaints relating to this issue have been reported. The three affected customers will be promptly notified.

APA4 Recall Campaign – Check connection points on the body and rework if necessary

Attachments

1. [VIN_List_Report_APA4_2023-05-30.xlsx](#)