

APA5 Recall Campaign - Re-programming instrument cluster

APA5 Recall Campaign - Re-programming instrument cluster

Please be advised that this Recall only affects vehicles originally sold in Puerto Rico.

ID Number	APA5
Models	Taycan (Y1A/ Y1B)
Model Years	2020-2023
VIN List	Attached
Number of Affected VINs	71
Issue Description	Due to an incorrect market-specific coding of instrument clusters for Puerto Rico, the brake wear symbol is not displayed as legally required on the subject vehicles.
What Dealers Should do	Please arrange for customer vehicles to have the campaign carried out as soon as possible.
What will Porsche do?	Vehicles will have the remedy performed once it is available.
TI Number	No. 80-23
Customer letter	To be posted at a later date.
Customer Reactive Statement	Our highest priority is the safety of our cars. We have identified an issue affecting the instrument cluster in the 2020-2023 Taycan cars in Puerto Rico. Due to incorrect market-specific programming, the brake wear symbol is not displayed as designed. Our Puerto Rico customers will be promptly notified so that Porsche dealers can reprogram the instrument clusters. The recall remedy is free.

Attachments

1. [PR VIN_List_Report_APA5_2023-06-12.xlsx](#)