

Recall 23KWF: Cummins PX-9 Fuel Hose

[Edit](#) [Clone](#)

Number

23KWF / 23V617 / 2023-495 / C2717

Supplier

Cummins

Description

Cummins PX-9 Fuel Hose

Date

9/20/2023

What's New

Safety Recall

Reference Cummins Recall C2717. Kenworth has been alerted to a defect in certain PX-9 remote fuel filter hoses installed on Model Year 2023-2024 T280, T380, and T480 chassis. The hoses could become disconnected, causing an engine stall and increasing the risk of a crash. Fuel leaks near an ignition source may increase the risk of fire. Refer to Cummins Recall C2717 for repair information.

Introduction

Cummins has alerted Kenworth to a defect which relates to motor vehicle safety in certain model year 2023 and 2024 T280, T380, and T480 vehicles. A fuel hose that becomes disconnected will result in an engine stall, increasing the risk of a crash. A fuel leak in the presence of an ignition source may increase the risk of a fire. Reference Cummins Recall C2717.

Situation

507 (458 U.S. and 49 Canada) Model Year 2023-2024 T280, T380 and T480 chassis built from 12/02/22 to 03/14/23 equipped with Cummins PX-9

engines.

Resolution

Safety Recall

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. In Service Management, select Campaign **2717** to add it to the case. If the unit is released back into service without performing the repair, make sure to also release the Campaign in Service Management
3. If you are not using Service Management to start repair orders, review SIR for "Complete" or "In Process" next to the **2717** campaign code prior to performing this repair.
4. Follow the procedures in Cummins C2717 Safety Recall to replace the fuel hoses. Go to Cummins QuickServe and refer to the Cummins Recall – C2717.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

Go to Cummins QuickServe and refer to the Cummins Recall C2717. File warranty claims through the Cummins warranty system. SIR will indicate chassis involved in this recall with the designator of "2717 " in the campaign field.

Procedure

Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained.

Please refer to Cummins QuickServe for repair procedure. **Reference Cummins Recall C2717.**

Links

[Chassis List](#)