



IMPORTANT SAFETY RECALL

This notice applies to your vehicle(s) with the VIN(s) indicated on the enclosed owner response cards.

AUTOCAR, LLC RECALL ACX-2310 DC-2308
NHTSA RECALL 23V656
November 2023

Dear Autocar Truck Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has decided that a defect which relates to motor vehicle safety exists in certain, 2022-2023 model year ACX (Xpeditor) and DC (Legend) chassis. The ACX chassis were manufactured between March 11, 2022, and June 27, 2023, with non-sequential serial numbers in the range of 238058 through 245684. The DC chassis were manufactured between April 20, 2022, and June 1, 2023, with non-sequential serial numbers in the range of 239500 through 245684. Our records indicate that your vehicle was manufactured within this time and may contain the defect described herein.

MODELS AFFECTED: Autocar ACX (Xpeditor) and DC (Legend) MY 2022-2023

COMPONENTS AFFECTED: The steering column shaft pinch bolt may not be properly secured.

SAFETY DEFECTS AND POTENTIAL RISKS: If the steering column shaft pinch bolt is not properly secured, it could come into contact with cab components and cause the steering to bind, resulting in a sudden loss of steering, increasing the risk of a crash.

REPAIR REQUIRED: The steering column shaft pinch bolts will be secured or replaced at no charge.

TIME REQUIRED FOR THE REPAIR: The labor time to repair your vehicle is 1.0 hour.

WHAT YOU SHOULD DO: To have your vehicle repaired, contact your local authorized Autocar service site or email warranty@autocartruck.com.

ACF 00002 Rev. 000



PRIOR REPAIRS:

If you have previously paid for repairs relating to this recall you may be entitled to recover the amount you paid for those repairs. Submit a copy of all documentation supporting your claim to Autocar at the address set forth below in the "Assistance" section.

**NOTICE
REGARDING
LEASED
VEHICLES:**

If you are a Lessor (as defined below) of a vehicle that is affected by this notice, you are obligated under federal law to provide a copy of this Notice to the lessee of such vehicle within 10 days of your receipt of this Notice. Further, you must maintain a record, which identifies the lessee(s) to whom you send a copy of this Notice, the date you send the Notice and the VIN of the vehicle that you have leased to the lessee(s).

For purposes of this Notice, the term "Lessor" means a person or entity that is the owner, as reflected on the vehicle's title, of any five or more leased vehicles, as of the date of this Notice.

**OWNER RECALL
RESPONSE
CARD:**

The enclosed Owner Recall Response Card identifies your vehicle. Please complete this postage-paid card and return it to Autocar. If you do not own, have sold, or have traded the vehicle identified on the card, please indicate that on the postage-paid card and return it to Autocar.

ASSISTANCE:

If you need assistance with this recall, call our toll-free numbers below or write to Autocar at:

Autocar, LLC
Service & Warranty Departments
551 S. Washington St.
Hagerstown, Indiana 47346
888-218-3611 (Toll Free)
877-973-3486 (Toll Free)

You may also submit a complaint to:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE
Washington, DC 20590

or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 800-424-9153); or go to.

We regret any inconvenience this recall may cause, but we hope you recognize Autocar's concern for your safety and satisfaction with your vehicle.

Sincerely,

AUTOCAR, LLC

ACF 00002 Rev. 000