




*****AUTO**MIXED AADC 530 P1 C1 ## 0183



IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN # 

February 2, 2024

Harley-Davidson Recall No. 0183

NHTSA Recall No. 23V666

Dear Harley-Davidson® Motorcycle Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Harley-Davidson Motor Company, Inc. has decided that a defect which relates to motor vehicle safety exists in certain model year 2023 X350 RA (Riding Academy) motorcycles. We are notifying you because our records indicate that you may own one of these motorcycles.

What is the Issue?

The fuel sensor on your motorcycle may leak. A fuel leak in the presence of an ignition source may lead to a fire.

What Should You Do?

Remedy parts for this condition are now available. Please arrange to have the fuel level sensor gasket on your motorcycle replaced. Dealers will be reimbursed for the repair which should take less than one hour. Once the service has been completed, you will be requested to sign a recall claim.

IMPORTANT: : If you choose to operate the motorcycle before this safety recall repair has been completed, we recommend that you inspect the underside of the fuel tank to ensure no active fuel leak is present.

If you have sold your motorcycle and have an address for the current owner, it is important that you forward this notice to the new owner. Alternatively, you may contact us at the Harley-Davidson phone numbers listed below and provide us with the new contact

information so that we may notify the new owner of this recall.

What If You Have Additional Questions or Concerns?

For more information regarding eligibility, or if you are unable to perform the required service to your satisfaction, please contact Harley-Davidson Motor Company, Inc. for immediate assistance at 1-800-258-2464.

If you are unable to obtain a remedy for the defect without charge in a reasonable time, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590; or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this may cause you, but we are initiating this action in the interest of personal safety and satisfaction with our products. Thank you for your cooperation.

Sincerely,

Harley-Davidson Motor Company, Inc.
Recall 0183



*****AUTO**MIXED AADC 530 P1 C1 0183

RIDERS EDGE KHD Inc.
1 Chelmsford Rd.
North Billerica MA 01862-2108



IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN # LBB4W4CJ0P2500356

February 2, 2024

Harley-Davidson Recall No. 0183

NHTSA Recall No. 23V666

Dear Harley-Davidson® Motorcycle Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Harley-Davidson Motor Company, Inc. has decided that a defect which relates to motor vehicle safety exists in certain model year 2023 X350 RA (Riding Academy) motorcycles. We are notifying you because our records indicate that you may own one of these motorcycles.

What is the Issue?

The fuel sensor on your motorcycle may leak. A fuel leak in the presence of an ignition source may lead to a fire.

What Should You Do?

Remedy parts for this condition are now available. Please arrange to have the fuel level sensor gasket on your motorcycle replaced. Dealers will be reimbursed for the repair which should take less than one hour. Once the service has been completed, you will be requested to sign a recall claim.

IMPORTANT: : If you choose to operate the motorcycle before this safety recall repair has been completed, we recommend that you inspect the underside of the fuel tank to ensure no active fuel leak is present.

If you have sold your motorcycle and have an address for the current owner, it is important that you forward this notice to the new owner. Alternatively, you may contact us at the Harley-Davidson phone numbers listed below and provide us with the new contact

information so that we may notify the new owner of this recall.

What If You Have Additional Questions or Concerns?

For more information regarding eligibility, or if you are unable to perform the required service to your satisfaction, please contact Harley-Davidson Motor Company, Inc. for immediate assistance at 1-800-258-2464.

If you are unable to obtain a remedy for the defect without charge in a reasonable time, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590; or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this may cause you, but we are initiating this action in the interest of personal safety and satisfaction with our products. Thank you for your cooperation.

Sincerely,

Harley-Davidson Motor Company, Inc.
Recall 0183



*****AUTO**MIXED AADC 530 P1 C1 0183

RIDERS EDGE KHD Inc.
1 Chelmsford Rd.
North Billerica MA 01862-2108



IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN # LBB4W4CJ1P2500317

February 2, 2024
Harley-Davidson Recall No. 0183
NHTSA Recall No. 23V666

Dear Harley-Davidson® Motorcycle Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Harley-Davidson Motor Company, Inc. has decided that a defect which relates to motor vehicle safety exists in certain model year 2023 X350 RA (Riding Academy) motorcycles. We are notifying you because our records indicate that you may own one of these motorcycles.

What is the Issue?

The fuel sensor on your motorcycle may leak. A fuel leak in the presence of an ignition source may lead to a fire.

What Should You Do?

Remedy parts for this condition are now available. Please arrange to have the fuel level sensor gasket on your motorcycle replaced. Dealers will be reimbursed for the repair which should take less than one hour. Once the service has been completed, you will be requested to sign a recall claim.

IMPORTANT: : If you choose to operate the motorcycle before this safety recall repair has been completed, we recommend that you inspect the underside of the fuel tank to ensure no active fuel leak is present.

If you have sold your motorcycle and have an address for the current owner, it is important that you forward this notice to the new owner. Alternatively, you may contact us at the Harley-Davidson phone numbers listed below and provide us with the new contact

information so that we may notify the new owner of this recall.

What If You Have Additional Questions or Concerns?

For more information regarding eligibility, or if you are unable to perform the required service to your satisfaction, please contact Harley-Davidson Motor Company, Inc. for immediate assistance at 1-800-258-2464.

If you are unable to obtain a remedy for the defect without charge in a reasonable time, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590; or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this may cause you, but we are initiating this action in the interest of personal safety and satisfaction with our products. Thank you for your cooperation.

Sincerely,

Harley-Davidson Motor Company, Inc.
Recall 0183