

EQUIPMENT SAFETY RECALL – NORTH AMERICA
High Pressure Fuel Pump - Equipment



Reference: 02A / NHTSA 23E-032

FCA US LLC

Parts Recalled Mopar High Pressure Fuel Pump 68501449AA, Mopar 3.0L Diesel Engine 05162119BB, Mopar 3.0L Diesel Engine 05162111CB, Mopar 3.0L Diesel Engine 05158048AH, Mopar 3.0L Diesel Engine 05158052AG intended for use on some 2022-2023 DT Ram 1500 Pickup and 2021-2023 JL Wrangler and JT Gladiator vehicles.

Revision	Edition	Detail
0	November 2023	Initial Version.

Template Version 1.8

SYMPTOM DESCRIPTION

Some of the High Pressure Fuel Pumps (HPFPs) listed above could fail prematurely. A high-pressure fuel pump failure may introduce internally failed component debris into the fuel system potentially causing fuel starvation if installed into a vehicle. Vehicle occupants may notice a Malfunction Indicator Lamp, service Electronic Throttle Control indicator, a fuel leak at the HPFP, or excessive noise from the HPFP. **Fuel starvation may result in an unexpected loss of motive power, which can cause a vehicle crash without prior warning.**

REPAIR TO BE PERFORMED

Inspect the pump part number:

Part number Mopar High Pressure Fuel Pump 68501449AA, Mopar 3.0L Diesel Engine 05162119BB, Mopar 3.0L Diesel Engine 05162111CB, Mopar 3.0L Diesel Engine 05158048AH and Mopar 3.0L Diesel Engine 05158052AG - Pump or engine suspect, repurchase the pump or engine.

Dealer should add part (reimbursement) to claim when using LOP.

If the recalled HPFP or remanufactured engine assembly with part number listed above has been installed into a vehicle, the repair will be covered under recall 01A.

COMPLETION REPORTING / REIMBURSEMENT

Claims for vehicles that have been serviced must be submitted on the DealerCONNECT Claim Entry Screen located on the Service tab. Claims paid will be used by FCA to record recall service completions and provide dealer payments.

Use the following labor operation numbers and time allowances:

Labor Description	Number	Hrs
Inspect High Pressure Fuel Pump Part Number	14-02-A1-81	0.0
█ Handling Fee for Equipment Safety Recall 02A	95-14-02-50	█

NOTE: See the Warranty Administration Manual, Recall Claim Processing Section, for complete recall claim processing instructions.

PARTS RETURN

No parts return required for this campaign. Render the recalled part unusable and discard.

SPECIAL TOOLS

No special tools required for this campaign.

DEALER NOTIFICATION

To view this notification on DealerCONNECT, select “Global Recall System” on the Service tab, then click on the description of this notification.

OWNER NOTIFICATION / SERVICE SCHEDULING

All involved vehicle owners known to FCA are being notified of the service requirement by first class mail. They are requested to schedule appointments for this service with their dealers. A generic copy of the owner letter is attached.

ADDITIONAL INFORMATION

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Services / Field Operations
FCA US LLC.

Strictly respect STELLANTIS Group safety, cleanliness, and environmental instructions for any vehicle service.
Document exclusively reserved for dealer information. Internal distribution to be ensured by dealer.
Reproduction forbidden without the written agreement of STELLANTIS Group. (C) 2023 STELLANTIS Group. All Rights Reserved
(XXX)

IMPORTANT SAFETY RECALL

High Pressure Fuel Pump

02A/NHTSA 23E-032

Dear [Name],

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

FCA has decided that a defect, which relates to motor vehicle safety, exists in certain **High Pressure Fuel Pumps**: Mopar High Pressure Fuel Pump 68501449AA, Mopar 3.0L Diesel Engine 05162119BB, Mopar 3.0L Diesel Engine 05162111CB, Mopar 3.0L Diesel Engine 05158048AH and Mopar 3.0L Diesel Engine 05158052AG intended for use on some 2022-2023 DT Ram 1500 Pickup and 2021-2023 JL Wrangler and JT Gladiator vehicles.

It is extremely important to take steps now to repair your vehicle to ensure the safety of you and your passengers.

YOUR SCHEDULING OPTIONS

- 1. RECOMMENDED OPTION**
Call your authorized Chrysler / Dodge / Jeep® / RAM Dealership
- 2. Call the FCA Recall Assistance Center at 1-800-853-1403.** An agent can confirm part availability and help schedule an appointment.
- 3. Visit recalls.mopar.com or download the Mopar Owner's Companion App.**

Get access to recall notifications, locate your nearest dealer, and more through this website or Mopar Owner's Companion App. You will be asked to provide your Vehicle Identification Number (VIN) to protect and verify your identity.

DEALERSHIP INSTRUCTIONS

Please reference Safety Recall 02A.

WHY DOES MY VEHICLE NEED REPAIRS?

FCA records indicate that you may have purchased a MOPAR high pressure fuel pump (HPFP) or engine assembly with an installed HPFP for your vehicle ^[1]. Some HPFPs could fail prematurely. A high-pressure fuel pump failure may introduce internally failed component debris into the fuel system potentially causing fuel starvation if installed into a vehicle. Vehicle occupants may notice a Malfunction Indicator Lamp, service Electronic Throttle Control indicator, a fuel leak at the HPFP, or excessive noise from the HPFP. **Fuel starvation may result in an unexpected loss of motive power, which can cause a vehicle crash without prior warning.**

HOW DO I RESOLVE THIS IMPORTANT SAFETY ISSUE?

If you purchased an HPFP, or a remanufactured engine with an HPFP on it and have not yet installed it, FCA will reimburse your purchase with the return of the HPFP or remanufactured engine assembly.

If the recalled HPFP or remanufactured engine assembly with part number listed above has been installed into a vehicle, the repair will be covered under recall 01A.

Please bring your HPFP or remanufactured engine assembly, and this letter with you to your dealership.

**TO SCHEDULE YOUR FREE REPAIR,
CALL YOUR CHRYSLER, DODGE, JEEP OR RAM DEALER TODAY**

WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?

If you have already experienced this specific condition and have paid to have it repaired, you may visit www.fcarecallreimbursement.com to submit your reimbursement request online. ^[3] Once we receive and verify the required documents, reimbursement will be sent to you within 60 days. If you have had previous repairs performed and/or already received reimbursement, you may still need to have the recall repair performed.

We apologize for any inconvenience but are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Assistance/Field Operations
FCA US LLC



Mr. Mrs. Customer
1234 Main Street
Hometown, MI 48371

[1] If you no longer own this vehicle, please help us update our records. Call the FCA Recall Assistance Center at 1-800-853-1403 to update your information.

[2] If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590, or you can call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to safercar.gov.

[3] You can also mail in your original receipts and proof of payment to the following address for reimbursement consideration: FCA Customer Assistance, P.O. Box 21-8004, Auburn Hills, MI 48321-8007, Attention: Recall Reimbursement.

Note to lessors receiving this recall notice: Federal regulation requires that you forward this recall notice to the lessee within 10 days.