

# Parts Bulletin

TITLE:

**Recall R10245 Ball Joint  
Model Year: 2023 Polestar 2**

**GROUP:  
61**

**NO:  
R10245**

**CAR MARKET:  
US/CAN**

REVISIONS:

**ISSUE DATE:  
2023-07-12**

**STATUS DATE:  
2023-07-12**

Page 1 of 1

**Reference Bulletins: QB R10245**

Polestar Automotive USA on behalf of Polestar Performance AB, have decided to launch Recall R10245 on certain model year 2023 Polestar 2 vehicles.

Polestar investigations have shown a potential issue with the front left ball joint connecting the front lower control arm (FLCA) with the steering knuckle may have been installed incorrectly.

As a result, if the FLCA disconnects from the steering knuckle while driving, the vehicle's maneuverability may be reduced, increasing the risk of a crash.

To remedy concerned vehicles, Polestar will inspect the front left ball joint to ensure that the fastening bolt connecting the FLCA to the steering knuckle is installed correctly and change the fastening bolt if necessary.

A total of 3 U.S. and 18 Canadian Vehicles are eligible for this recall.

The following part numbers apply:

Part Number	Description	Qty
30746632	Screw	1