

## RECALL H448 – HIGH VOLTAGE COOLANT HEATER FAILURE

## SAFETY RECALL H448 – HIGH VOLTAGE COOLANT HEATER FAILURE

AFFECTED MODELS	20-22MY I-PACE
VOLUME AFFECTED	US 668 CAN 11
REPAIR	A concern has been identified on certain vehicles without heated front windshield where the High Voltage Coolant Heater (HVCH) can fail to operate. Where the HVCH fails coolant cannot be heated and the windshield will not be defrosted. A replacement of the HV heater is required.
REPAIR TIME	6.0 hrs + DIDO
CAMPAIGN LAUNCH	Retailer Admin Bulletin Notification: August 8th, 2023 Repair service bulletin is expected around mid-October 2023 pending receipt of required parts.
Notes	Owners were notified via interim mailing on September 20th, 2023