



VOLUNTARY RECALL CAMPAIGN

Classification: BR23-003	Reference: NTB23-084	Date: November 27, 2023
-----------------------------	-------------------------	----------------------------

VOLUNTARY SAFETY RECALL CAMPAIGN 2021 ROGUE; REAR BRAKE CALIPERS

CAMPAIGN ID #: PC993
APPLIED VEHICLES: 2021 Rogue (T33)

**Check Service COMM or Dealer Business Systems (DBS)
National Service History to confirm campaign eligibility.**

INTRODUCTION

Nissan is conducting this voluntary safety recall campaign on certain specific model year 2021 Rogue vehicles to replace the rear brake caliper assemblies. This service will be performed at no charge to the customer for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number PC993 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service COMM or Dealer Business Systems (DBS) National Service History for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. **Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration.** While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

IMPORTANT: Follow all cautions, warnings, and notes in the ESM when working on the brake system.

1. Replace both rear brake caliper assemblies.
 - Refer to the ESM: **BRAKES > BRAKE SYSTEM > REMOVAL AND INSTALLATION > REAR DISC BRAKE > BRAKE CALIPER ASSEMBLY**

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
BRAKE ASSY-DISC, RR RH Rear Brake Caliper Assembly (RH)	D4000-6RA0C	1
BRAKE ASSY-DISC, RR LH Rear Brake Caliper Assembly (LH)	D4010-6RA0C	1
Gasket-Brake Hose	46237-AV601	4
Nissan Genuine Brake Fluid (DOT3)	999MP-A4100P (1)	As needed

- (1) Order this item through the Nissan Maintenance Advantage program: Phone 877-NIS-NMA1 (877-647-6621). Website order via link on the dealer portal; www.NNAnet.com and click on the "Maintenance Advantage-Tire/Battery/Chemical" link.

CLAIMS INFORMATION

Submit a "CM" line claim using the following claims coding:

CAMPAIGN ("CM") ID	DESCRIPTION	OP CODE	FRT
PC993	Replace Both Rear Brake Caliper Assemblies	PC9930	1.8

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 27, 2023	NTB23-084	Original bulletin published