



August, 2025

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2023 Bronco Sport has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number**    **23S01 - Continental ABS Valve Leakage**  
**and Description:**

**What is the issue?**            On your vehicle, it may be possible for a valve within the anti-lock brake system's hydraulic control unit to have an internal leak. This condition may be intermittent, resulting in inconsistent pedal travel. Additionally, the driver selectable Auto Vehicle Hold feature may not operate as intended if a leak is present.

An unexpected increase in brake travel or unexpected movement during an Auto Hold event can increase the risk of a crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Augusto de, 2025

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2023 Bronco Sport las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:**            **23S01 - Fuga en la válvula de ABS de Continental**

**¿Cuál es el problema?**            Es posible que exista una fuga interna en una válvula dentro de la unidad de control hidráulico del sistema de frenos antibloqueo de su vehículo. Esta condición podría ser intermitente, lo cual se traduce en un recorrido no uniforme del pedal. Adicionalmente, la función de detención automática seleccionable por el conductor podría no funcionar según lo previsto si hay una fuga presente.

Un aumento inesperado del recorrido del freno o un movimiento inesperado durante un evento de detención automática puede aumentar el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).

Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0073510 A / 000000000000321 / 321



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

