



August, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2023 Edge has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 23C09 - Child Seat Tether Suspect Welds
and Description:

What is the issue? On your vehicle, the second row 60% seat-back frame may have a suspect child seat tether wire weld.

Seat back assemblies with suspect child seat tether wire welds may experience degradation in tether anchorage load carrying capability. A child seat tether with a reduced load carrying capability can increase the risk of injury in a crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Augusto de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2023 Edge las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 23C09 - Soldaduras sospechosas de la correa del asiento para niños

¿Cuál es el problema? El bastidor del respaldo del asiento 60 % de la segunda fila de su vehículo podría tener una soldadura sospechosa en el cable de la correa del asiento para niños.

Los ensambles de los respaldos con soldaduras sospechosas en el cable de la correa del asiento para niños podrían experimentar degradación en la capacidad de transporte de carga del anclaje de la correa. Una correa de un asiento para niños con una capacidad de carga reducida puede aumentar el riesgo de sufrir lesiones en caso de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0491850 A / 000000000000320 / 320



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

