



**RECREATIONAL VEHICLE  
SAFETY RECALL NOTICE**

Safety Recall: 23V-376  
Safety Advisory: 23-444  
April 22, 2026

**IMPORTANT SAFETY RECALL – 7th Notice**

«POLKNAME»  
«POLKADDRESS»  
«POLKCITY», «POLKST» «POLKZIPPLUS4»



This notice applies to your vehicle: «VIN»

Dear «POLKNAME»:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

**Our records indicate  
YOUR UNIT HAS NOT BEEN  
REMEDIED.  
Please **DO NOT** ignore this notice!**

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model 2021-2023 Arcadia Fifth Wheels. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for  
this recall***

It has been decided that the vehicles in the recall population may not have a backer board behind the cabinet front for the wardrobe slide in the bedroom. Under certain conditions if the backer board is not installed into the slide box framing and the cabinet front detaches, the slide room can completely extend out of the opening; leading to an increased risk of personal injury.

***What we  
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to inspect units to verify that the backer board is missing. If the backer board is missing steel brackets will need to be securely mounted in each corner, on the sides of the slide box, to stop the slide room when opening. The service and parts required for this corrective action will be provided at no charge to you.

***What we  
need you to  
do***

If the cabinet front is loose, do not fully extend the slide room until the steel brackets can be added to the wardrobe slide box. As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 2 hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

**BE ADVISED –  
Damage caused by failure to have the  
recall remedy completed will be the  
responsibility of the owner.**

***If you have  
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.nhtsa.gov>.) Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this RV, please call Keystone Customer Service at 1-866-425-4369 or email [recall@keystonerv.com](mailto:recall@keystonerv.com) with your name and VIN.

Thank you for your attention and cooperation in this matter.

Sincerely,

**KEYSTONE RV COMPANY**

cc: National Highway Traffic Safety Administration (NHTSA)

