



March, 2025

**\* \* \* IMPORTANT SAFETY RECALL REMINDER \* \* \***

According to our records, your 2024 Mustang has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number**    **23S61 - 2024 Mustang Brake Pedal Loose**  
**and Description:**

**What is the issue?**            In some of the affected vehicles, the brake pedal pivot tube may not have been properly flared. Missing flares can cause the brake pedal pivot tube to become unseated, resulting in a loose brake pedal.

A loose brake pedal can result in a degradation or loss of braking function, which can increase the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Marzo de, 2025

**\* \* \* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \* \* \***

SegUR nuestros registros, no se realizaron en sur 2024 Mustang las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:**            **23S61 - Pedal de freno Mustang 2024 flojo**

**¿Cuál es el problema?**            En algunos de los vehículos afectados, es posible que el tubo de pivote del pedal del freno no haya sido ensanchado correctamente. La falta de ensanchamientos puede hacer que el tubo de pivote del pedal del freno se suelte, lo que provocará que el pedal del freno se afloje.

Un pedal de freno flojo puede provocar una degradación o pérdida de la función de frenado, lo cual puede aumentar el riesgo de accidente.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).


Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0620978 A / 000000000000601 / 601



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

