



March, 2025

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2022 Maverick has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **23C41 - 2022-24 Maverick Turn Signal Failure**
and Description:

What is the issue? The turn signal outage detection system may not send a notification to the driver if only one of the two rear turn signal lamp bulbs on either side has failed.

This may result in you being unaware of a turn signal bulb failure, which may not alert other road users of an upcoming turn or lane change, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Marzo de, 2025

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2022 Maverick las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **23C41 - Maverick 2022-24 - Falla en la luz direccional**

¿Cuál es el problema? Es posible que el sistema de detección de interrupción de las luces direccionales no envíe una notificación al conductor si solo uno de los dos focos de las luces direccionales traseras en cada lado ha fallado.

El resultado de esto podría ser que usted no se dé cuenta de la falla en el foco de la luz direccional, lo que podría no alertar a otros usuarios de la carretera sobre un próximo giro o cambio de carril, aumentando el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0655719 A / 000000000000545 / 545



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

