

May 30, 2025

Version 6

Safety Recall: 2018–19 Accord Front Seat Belt Buckle Repairs

This Service Bulletin was replaced by Service Bulletins 25-031, Safety Recall: 2018-19 Accord Driver's Seat Belt Buckle Replacement and 25-030, Safety Recall: 2018-19 Accord Passenger's Seat Belt Buckle Replacement dated May 1, 2025.

AFFECTED VEHICLES

Year	Model	Trim Level	VIN Range
2018–19	Accord	ALL	Check the iN VIN status for eligibility.


BACKGROUND

Due to improper manufacturing of the seat belt buckle channel, the front seat belt buckles may not latch properly. An improperly latched seat belt buckle may not securely restrain occupant(s) during a collision.

WARRANTY CLAIM INFORMATION

For repairs before or on **May 29, 2025**, you must use the warranty claim information within this bulletin. For repairs on or **after May 30, 2025**, go to the respective Service Bulletins mentioned above, depending on the required repair.

TEST CODE FIELD



The screenshot shows a software interface for repair information. At the top, there is a 'Repair Information' header with a 'View Flat Rate Labor Time' checkbox. Below this is a 'Test Code' field with a red error icon. A dashed box labeled 'TEST CODE FIELD' with an arrow points to this field. Below the test code field is a table with the following data:

Item	Labor Operation No.	Labor Description	Time
1	8555A6	SAFETY RECALL CAMPAIGN: DRIVER SEATBELT BUTTON, REPLACE (INCLUDES INSPECTION)	0.4
2			
3			
Total Time			0.4

At the bottom of the form, there is a section for 'Diagnostic Trouble Codes' with a dropdown menu set to 'NO' and several empty input fields.

Seat Belt Button Repair

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8555A6	Driver Seat Belt Button Replace (Includes: Function, DTC Indicator, and Residue check).	0.4hr	6XL00	NDA00	A23016A	04816-TVA-A20ZA
8655A2	Passenger Seat Belt Button Replace (Includes: Function, DTC Indicator, and Residue check).	0.4hr	6XR00	TDF00	A23016B	04813-TVA-A10ZA

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

Seat Belt Buckle Replacement + Inspection

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8551F6	Driver Seat Belt Buckle Replace (Includes: Inspection).	0.5hr	6XL00	NDA00	A23016C	04816-TVA-A20ZA
A	For Buckle causing DTC check and troubleshooting only (any other DTC normal troubleshooting applies).	0.3hr		NDA00	A23016D	
8651A5	Passenger Seat Belt Buckle Replace (includes Inspection, Seat weight calibration, and Steering angle learn).	0.6hr	6XR00	TDF00	A23016E	04813-TVA-A10ZA
A	For Buckle causing DTC check and troubleshooting only (any other DTC normal troubleshooting applies).	0.3hr		TDF00	A23016F	

NOTE:

- Due to seat belt part number variation for each model trim, you may add the seat belt part number to the template.