

23PBC - Bendix Intellipark: NHTSA #23V185

 [Edit](#)  [Clone](#)

Number

23PBC

Supplier

Bendix

Description

23PBC - Bendix Intellipark: NHTSA #23V185

Date

4/3/2023

What's New

Safety Recall - Certain tractors equipped with Bendix Intellipark Tractor Park Valve Module (PVM) may intermittently become stuck in the un-parked position and may not transition from un-parked to parked when the park switch is pulled on the vehicle dashboard.

Warning which can precede or occur: Park indication LEDs on the park switch remain off after the park switch is pulled indicating that the spring brake system has not exhausted, and the vehicle is not parked. Audible exhaust sounds that typically are heard as an air-braked vehicle is parked will not be heard indicating that the vehicle is not parked.

Interim Notification

This is to inform dealers of the existence of a safety recall. This bulletin will be updated when repair procedures are developed, and necessary parts are available.

Situation

25 (25 U.S. Only) 2023 to 2024 Model Year 579 chassis manufactured between 07/27/2022 and 02/03/2023.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Links

[23PBC Chassis List](#)

Authored by D. Cook