

July 7, 2023

Version 2

Safety Recall: Multi-Model Brake Hold/VSA Modulator Stop Sale

This bulletin has been replaced by the service bulletins identified below:

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2023	Integra	ALL	Check the iN VIN status for eligibility
2023	RDX	ALL	Check the iN VIN status for eligibility

BACKGROUND

A ball valve in the vehicle stability assist (VSA) modulator was damaged during the manufacturing process, resulting in an insufficient seal on part of the *Brake Hold* system. (This issue does not affect regular service brake functions.) The insufficient seal potentially could result in brake fluid leakage in the VSA modulator. If leakage occurs with the *Brake Hold* function engaged (i.e., when the system keeps brake pressure on without the brake pedal depressed), the vehicle unexpectedly may move at low speed, increasing the risk of a crash that may result in damage to involved vehicle(s) or injury to occupant(s) or others.

NOTE: All affected vehicles have moved from this bulletin to the following service bulletins. Vehicles are still considered **Stop Sale** until they are repaired under the new remedy service bulletins identified below:

- 23-027 Safety Recall: 2023 Integra Brake Hold/VSA Modulator
- 23-028 Safety Recall: 2023 RDX Brake Hold/VSA Modulator

END

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.