

IMPORTANT SAFETY RECALL INFORMATION

Issued in Accordance
With Federal Law
U.S. Department of Transportation



T1 P1 0001

-23PBC

Safety Recall Notice: 23PBC

IMPORTANT SAFETY RECALL

Interim Notification

Subject: Safety Recall: 23PBC - Bendix Intellipark recall

NHTSA: 23V185

EXPIRATION DATE: NONE

This notice applies to your vehicle. Your VIN(s) can be found on the bottom or back of this page.

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt has decided that a defect which relates to motor vehicle safety exists in certain 2023 to 2024 Model Year 579 tractor chassis built from 07/27/2022 through 02/03/2023 and equipped with the Bendix Intellipark option. The Bendix Intellipark Tractor Park Valve Module (PVM) may intermittently become stuck in the un-parked position and may not transition from unparked to parked when the park switch is pulled on the vehicle dashboard.

An Intellipark PVM that is stuck in the un-parked position does not allow the vehicle spring brakes to exhaust when the operator pulls the park switch. In order to park the vehicle, the operator must deplete air storage in the air brake system by fanning-down the service brake pedal. If an operator does not properly fan down the brakes, the vehicle may move unexpectedly, which may increase the risk of a crash.

What is the problem? The Bendix Intellipark Tractor Park Valve Module (PVM) may intermittently become stuck in the un-parked

position.

What will your dealer do? When the repair procedure and parts are available, your dealer will replace the necessary parts per the

decided repair procedure.

What should you do? There is no action required on your part at this time. You will receive a letter notifying you when the repair

procedure and parts are available.

Peterbilt Motors Company has initiated this recall to remedy the issue with no charge to you. **Currently, the repair procedure is unavailable to correct this condition**. However, Peterbilt is required to notify customers of the existence of the identified safety defect. **You will be notified by mail when the repair procedure and parts become available**.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall, or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St, Denton, TX 76205, Attn: Customer Experience Department.

If you conclude that Peterbilt has not enabled you to remedy this defect in a reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner. Please send all known ownership and address changes to PBDiv.Warranty.Docs@paccar.com.

We apologize for any inconvenience this preventive procedure may cause and thank you for your participation in helping Peterbilt provide the highest levels of customer satisfaction and service expertise. We value your business and appreciate your ongoing loyalty to Peterbilt and its dealer network. Industry-leading quality, performance and reliability are hallmarks of Peterbilt products, and we thank you for making Peterbilt your truck of choice.

Sincerely,

Michelle Ponsonby

Director of Customer Experience Peterbilt Motors Company

Scan this QR code to open the Peterbilt Dealer Locator.



Our records indicate that these vehicles are affected by 23PBC and are owned by