



IC Bus, LLC
2701 Navistar Drive
Lisle, IL 60532 USA

navistar.com



A NAVISTAR COMPANY

JULY 2023

IMPORTANT SAFETY RECALL 23517

INTERIM NOTICE

NHTSA RECALL NO. 23V397

This notice applies to your vehicle identified on the enclosed card.

Dear IC Bus Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

IC Bus has decided that a defect which relates to motor vehicle safety exists in certain IC Bus 2019 thru 2022 CE commercial buses built 11/26/2018 thru 01/05/2022, and 2019 thru 2024 TC commercial buses built 05/24/2018 thru 05/15/2023 with feature code 04100 (Brake system, hydraulic).

REASON FOR THIS RECALL

The brake pressure switch may allow brake fluid to seep past the diaphragm seal into the brake pressure switch electrical connector and associated fuse which can short the switch and/or fuse.

RISK TO MOTOR VEHICLE SAFETY

A shorted switch or fuse may cause the circuit to generate excessive heat which can result in an increased risk of a fire.

DEFECT REMEDY

A remedy has been determined. Parts have been ordered and will be available in early September, free of charge. When parts become available, you will be notified of additional actions you should take

ACTIONS YOU SHOULD TAKE

Until the recall remedy is performed, affected owners or operators are advised to park their vehicles outdoors.

This condition may also set a "service brake system" malfunction indicator lamp.

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

IF YOU NEED ASSISTANCE

IC Bus requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

IC Bus, LLC