

23V-253
Model Year 2023
BMW X5 SAV
Second Row Outboard Seat Head Restraints
In-Car / In-App Communication – Safety Recall Reminder
20 Jul 2023

Title:

BMW Non-Compliance Recall 23V-253: 2nd Row Head Restraints

Text:

The second-row seats have head restraints from the seat supplier that may not meet specifications. The head restraint guides may not have a locking tab. In certain crashes, if the head restraint were to move downward, this could increase the risk of injury.

Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.

Advise all drivers of this important information.

For the latest updates to this recall, please visit bmwusa.com/recall.

Short Text:

Important Non-Compliance 23V-253: 2nd Row Head Restraints. Contact an authorized BMW center immediately to get your vehicle repaired for FREE. For updates to this recall, please visit bmwusa.com/recall. Dealer locator: bmwusa.com/dealer.

Pop-Up:

Important Non-Compliance Recall: Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.