
Recall# 23V507_23S37 OTA Messaging




SYNC NOTIFICATIONS WHEN AUTOMATIC SOFTWARE UPDATES ARE TURNED OFF










Update Available Alert








Update Complete Details


FORDPASS NOTIFICATIONS WHEN AUTOMATIC SOFTWARE UPDATE ARE TURNED OFF












Update Available Alert Update Complete Alert

Update Complete Details

SYNC NOTIFICATIONS WHEN AUTOMATIC SOFTWARE UPDATES ARE TURNED ON










Update Complete Alert

Update Complete Details

FORDPASS NOTIFICATIONS WHEN AUTOMATIC SOFTWARE UPDATES ARE TURNED ON





11:14 🖊 ... 5G 🔳 SOFTWARE UPDATES **UPDATE SUCCESSFUL** Received Mar 5, 2024 Check out what's new! Ford vehicle Software Updates like this enhance the quality, capability and convenience of the vehicle. What's In This Update? Ford Power-Up Recall 23S37 We updated your front windows to fix a potential safety concern with those windows not automatically reversing when an obstruction is encountered in a low power condition. This completes safety recall 23S37. There is nothing more you need to do for this recall. Ford Power-Up software updates like this let us handle recalls without asking you to leave home. At Ford we value your safety. Priority Update 23-PU0721-WIN-OTU φ, 2 쉾 Home Vehicle Service Map

Update Complete Alert

Update Complete Details