

Safety Recall 23TA16

Your vehicle was previously inspected under a prior recall. Due to a problem with the inspection process specified by Toyota, the inspection may not have identified certain vehicles requiring the remedy. Without the remedy, the front passenger airbag may not deploy as designed. Your vehicle needs to be re-inspected. Toyota dealers will re-inspect with an improved process, and, if necessary, replace the instrument panel ***FREE OF CHARGE***. Contact your dealer ASAP.