

April 9, 2024

Mr. Brock Vander Veen Watson & Chalin Manufacturing, Inc. 500 Park Boulevard, Suite 1010 Itasca, IL 60143-1285

Subject: Bearing Journals May Not Be Fully Seated

Dear Mr. Vander Veen:

This letter serves to acknowledge Watson & Chalin Manufacturing, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: WATSON & CHALIN/SL2065/9999

Mfr's Report Date: April 3, 2024

NHTSA Campaign Number: 24E-031

Components: STEERING:LINKAGES:KNUCKLE:SPINDLE:ARM

Potential Number of Units Affected: 24

Problem Description:

Watson & Chalin Manufacturing, Inc. (W&C) is recalling certain SL2065 steerable lift axle suspension systems with a 20,000lb capacity. The bearing journals may not be fully seated into the left and right-side steering knuckle assembly.

Consequence:

A loose spindle may fracture, becoming a road hazard and increasing the risk of a crash.

Remedy:

W&C will work with commercial vehicle manufacturers and vehicle owners to provide and assist with the installation of replacement axle subassemblies, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact W&C customer service at 1-972-838-1266 or 1-972-547-6020. W&C's number for this recall is W&C 2024-01.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107KL 24E-031

Please ensure the following requirements are met:

Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (§ 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

AMENDED 573 REQUIRED.

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.



Watson & Chalin Manufacturing, Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Alae Andy

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

