

U.S. Department of Transportation

National Highway Traffic Safety Administration

May 23, 2024

Ms. Gina Gott Vermeer Manufacturing Company 1210 Vermeer Road East Pella, IA 50219 1200 New Jersey Avenue SE Washington, DC 20590

NEF-107HG 24V-357

Subject: Incorrect Lug Nut Torque Value in Service Manual

Dear Ms. Gott:

This letter serves to acknowledge Vermeer Manufacturing Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

VERMEER/BC900XL/2015-2022

Mfr's Report Date: May 21, 2024

NHTSA Campaign Number: 24V-357

Components:

EQUIPMENT:OTHER:OWNERS/SERVICE/OTHER MANUAL WHEELS:LUGS/NUTS/BOLTS/STUDS

Potential Number of Units Affected: 1.173

Problem Description:

Vermeer Manufacturing Company (Vermeer) is recalling certain 2015-2022 BC900XL brush chipper trailers. The service and maintenance manuals list the incorrect lug nut torque value.

Consequence:

Improperly tightened lug nuts can result in a loose or detached wheel, increasing the risk of a crash.

Remedy:

Vermeer will provide a remedy kit with a new manual, free of charge. Owner notification letters are expected to be mailed July 11, 2024. Owners may contact Vermeer customer service at 1-800-829-0051, ext. 7060. Vermeer's number for this recall is IK4561.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Vermeer Manufacturing Company's contact for this recall will be Hensly Guerra who may be reached by email at hensly.guerra1@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

