

# Recall Quarterly Report

# 24V862



U.S. Department  
of Transportation  
  
National Highway  
Traffic Safety  
Administration

**Manufacturer Name:** Mercedes-Benz USA, LLC  
**NHTSA Recall No. / MFR Recall No.:** 24V862 / 2024120005  
**Recall Subject:** Improperly Tightened Rear Axle Differential Bolts  
**Owner Notification Beginning Date:** Jan 10, 2025

## Quarterly Reports

Report #	Submission Date	Update Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	Jan 21, 2026	Jan 21, 2026	2025-4	3	2	0	0
3	Oct 08, 2025	Oct 08, 2025	2025-3	3	2	0	0
2	Jul 15, 2025	Jul 15, 2025	2025-2	3	2	0	0
1	Apr 02, 2025	Apr 02, 2025	2025-1	3	1	0	0

This document last updated: Jan 22, 2026

### Definitions:

**Report Quarter:** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

**Recall Population:** The total number of products recalled by the manufacturer.

**Total Remedied:** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable:** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed:** Products that have been scrapped, stolen, or exported.

