OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24E-045

Manufacturer Name: BMW of North America, LLC

NHTSA Recall No.: 24E-045

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: BMW of North America, LLC

Address: P.O. Box 1227

Westwood NJ 07675-1227

Company phone: 18005257417

Population:

Number of potentially involved : 5 Estimated percentage with defect : 100 %

Equipment Information:

Brand / Trade 1: BMW

Model: BMW Motorcycle Dealer Accessory Side Bag Holder for CE 02

Part No.: 77 49 5 A6B 236

Size: NR Function: NR

Descriptive Information: Approximately 5 dealer accessory side bag holders may have been delivered by

the supplier with bolts for mounting that do not correspond to specification.

Basis for recall population determination: Accessory sales records and parts logistics information were reviewed to determine the number of potentially affected side bag holders that may have been delivered to dealers or retailed to

customers.

Recall component difference to non-recall component: The dealer accessory side

bag holder requires longer bolts for mounting.

Production Dates: OCT 09, 2023 - MAY 28, 2024

Description of Defect:

Description of the Defect: This safety recall involves the dealer accessory side bag holder. The mounting

kit for the holder contains bolts that are shorter than specified. Therefore, the holder cannot be securely fixed to the motorcycle's rear frame. During riding, the holder (possibly with side bag attached) could detach from the motorcycle.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If the holder detached while riding, the holder, and possibly an attached side

bag, could become a hazard for road users and could increase the risk of a

crash.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name: Dealer Accessory Vario Side Bag Holder for CE 02

Component Description: Dealer Accessory Vario Side Bag Holder for CE 02

Component Part Number: 77 49 5 A6B 236

Supplier Identification:

Component Manufacturer

Name: SW-MOTECH-GmbH & Co. KG

Address: Ernteweg 7-10

Rauschenberg Foreign States 35282

Country: Germany

Chronology:

On May 21, 2024, a non-US dealer reported that the bolts contained in the accessory side bag holder kit were too short for proper mounting on the rear frame.

An engineering review was conducted and involved a comparison of drawing and CAD data which resulted in a discrepancy of bolt lengths. It was found that the CAD data had not been transferred correctly into the (build-to-print) drawing which was provided to the supplier.

On May 28, 2024, BMW decided to conduct a voluntary safety recall for the accessory side bag holder.

BMW has not received any customer complaints, field reports, or warranty claims in the US market that relate to this issue.

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries that relate to this issue.

Description of Remedy:

Description of Remedy Program: The bolts contained in the mounting kit will be replaced with bolts of the

correct length.

Owner notification is not necessary as potentially affected side bag holders

have not been retailed.

How Remedy Component Differs Dealer Accessory Vario Side Bag Holder for CE 02

from Recalled Component: part number 77 49 5 A6B 236

Identify How/When Recall Condition NR was Corrected in Production :

Recall Schedule:

Description of Recall Schedule: Dealer notification is planned to begin and end on June 4, 2024.

Owner notification is not necessary as potentially affected side bag

holders have not been retailed.

Planned Dealer Notification Date: JUN 04, 2024 - JUN 04, 2024

Planned Owner Notification Date: NR - NR

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: NR

Address: NR

NR

Country: NR

Company Phone: NR

^{*} NR - Not Reported