

Part 573 Safety Recall Report

24V-172

Manufacturer Name : Winnebago Industries, Inc.**Submission Date :** OCT 16, 2024**NHTSA Recall No. :** 24V-172**Manufacturer Recall No. :** 183**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc.

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 19

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2023-2024 Winnebago Sunstar

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by identifying Sunstar vehicles that had incorrect information programmed and printed on the certification label.

Production Dates : MAR 01, 2023 - JUL 30, 2023

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Certain Sunstar Motorhomes were built on a 22,000 GVW chassis w/ 235/80R tires and 22.5 x 7.5 Rims - 90PSI. These motorhomes received a label that stated 18,000 GVWR chassis w/ 245/70R tires and 19.5 x 6.75 Rims - 82PSI,

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : Using an incorrect tire size can increase the risk of a crash..

Description of the Cause : Incorrect programming for the affected motorhomes.

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Label-Certification

Component Description : Incomplete Vehicle Certification Label

Component Part Number : 087237-02

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On or about January 25, 2024, Winnebago was contacted by a customer who was questioning the accuracy of their tire size listed on the certification label. An investigation was initiated to determine the potential scope. On February 23, 2024 the Winnebago Product Safety Committee met and decided to issue a voluntary recall. Winnebago is not aware of any injuries as a result of the recall condition.

Description of Remedy :

Description of Remedy Program : Reimbursement request will fall under the general reimbursement plan on file with NHTSA

How Remedy Component Differs from Recalled Component : The remedy component will consist of a new certification label with correct weight and tire size information..

Identify How/When Recall Condition was Corrected in Production : The recall condition was corrected in production by changing the program used to print the labels.

Recall Schedule :

Description of Recall Schedule : The recall schedule will be within the 60 day requirement.

Planned Dealer Notification Date : MAR 12, 2024 - MAR 12, 2024

Planned Owner Notification Date : OCT 16, 2024 - OCT 16, 2024

* NR - Not Reported