

Part 573 Safety Recall Report

24V-209

Manufacturer Name : Chrysler (FCA US, LLC) (Stellantis)

Submission Date : MAR 19, 2024

NHTSA Recall No. : 24V-209

Manufacturer Recall No. : 32B



Manufacturer Information :

Manufacturer Name : Chrysler (FCA US, LLC) (Stellantis)

Address : 800 Chrysler Drive
CIMS 482-00-91 Auburn Hills MI
48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 1,201

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2024-2024 Dodge Hornet

Vehicle Type :

Body Style : SUV

Power Train : NR

Descriptive Information : Some 2024 MY Dodge Hornet vehicles may have been built with a manufacturer label that is missing rim and tire size designation information.

The suspect period began on January 15, 2024, when MY24 vehicle production began, and ended on February 13, 2024, when the label was updated to reflect the correct content. Vehicle assembly plant records were used to determine the suspect period.

Similar vehicles not included in this recall were built after the suspect period.

The total affected vehicles for this model is 1,189.

Production Dates : JAN 15, 2024 - FEB 13, 2024

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 2 : 2024-2024 Alfa Romeo Tonale

Vehicle Type :

Body Style : SUV

Power Train : NR

Descriptive Information : Some 2024 MY Alfa Romeo Tonale vehicles may have been built with a manufacturer label with missing rim and tire size designation information.

The suspect period began on January 15, 2024, when labels with missing information were introduced into vehicle production, and ended on February 10, 2024, when the label was updated to reflect the correct content. Vehicle assembly plant records were used to determine the suspect period.

Similar vehicles not included in this recall were built after the suspect period.

The total affected vehicles for this model is 12.

Production Dates : JAN 15, 2024 - FEB 10, 2024

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Noncompliance :

Description of the Noncompliance : Federal Motor Vehicle Safety Standard ("FMVSS") 571.110 S4.3.3 "Additional Labeling Information for Vehicles Other Than Passenger Cars" requires "Each vehicle shall show the size designation and, if applicable, the type designation of rims (not necessarily those on the vehicle) appropriate for the tire appropriate for use on that vehicle, including the tire installed as original equipment on the vehicle by the vehicle manufacturer" to be printed on the manufacturer label. Subject vehicles are equipped with a manufacturer label that is missing the size designation of the rims.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : A driver may use an incorrect rim size, which can increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : N/A

Involved Components :

Component Name 1 : Manufacturer Label

Component Description : Manufacturer Label

Component Part Number : 50573783

Supplier Identification :

Component Manufacturer

Name : Component manufactured by FCA

Address : NR

NR

Country : NR

Chronology :

- On February 26, 2024, Stellantis Europe S.p.A Customer Experience ("CX") was notified of a potential issue on certain vehicles related to missing Gross Vehicle Weight Rating, tire size, and rim size on the manufacturer label.
- From February 27, 2024, through March 8, 2024, Stellantis Europe S.p.A CX reviewed production data and assembly plant records and determined that some vehicles were built with missing manufacturer label information and determined the scope of vehicles affected.
- On March 7, 2024, the Stellantis Europe S.p.A organization recognized that the manufacturer label was missing required information on certain vehicles, potentially resulting in a noncompliance with FMVSS No. 110.
- On March 12, 2024, Stellantis Europe S.p.A determined, through the Vehicle Regulations Committee, to conduct a voluntary safety recall of the affected vehicles.

Description of Remedy :

Description of Remedy Program : FCA US will conduct a voluntary safety recall to apply a manufacturer label overlay with corrected information.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : This recall is not related to a part defect, but rather a manufacturing issue where the manufacturer label printed on the vehicle assembly was missing information.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : **03/19/2024: FCA US will notify dealers and begin notifying owners on or about 05/08/2024.

Planned Dealer Notification Date : MAY 08, 2024 - MAY 08, 2024

Planned Owner Notification Date : MAY 08, 2024 - MAY 08, 2024

* NR - Not Reported