

Part 573 Safety Recall Report

24V-257

Manufacturer Name : Airstream, Inc.

Submission Date : APR 09, 2024

NHTSA Recall No. : 24V-257

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Airstream, Inc.

Address : 419 West Pike Street
PO Box 629 Jackson Center OH
45334-0629

Company phone : 937-596-6111

Population :

Number of potentially involved : 172

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2024-2024 Airstream Pottery Barn

Vehicle Type : TRAILERS

Body Style : UNKNOWN

Power Train : NR

Descriptive Information : The recall population was determined by a review of vehicle records of the labels that were printed. - The information on the labels did not match the specifications of the GAWR.

Production Dates : JUL 24, 2023 - APR 01, 2024

VIN Range 1 : Begin : 1STJFYM20RJ569047 **End :** 1STJFYM21RJ572426 Not sequential

Description of Noncompliance :

Description of the Noncompliance : The rear axle weight information printed on the GAWR portion of the Federal Certification label is incorrect. The rear axle GAWR values were understated.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : This non-compliance may cause confusion to the owner of the vehicle. The owner may overload the axle which may lead to a crash.

Description of the Cause : The information on the label differs from the GAWR specifications.

Identification of Any Warning that can Occur : None

Involved Components :

Component Name 1 : Federal Certification Label

Component Description : Contains information relating to GAWR specifications

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

4/1//2024 - Airstream identifies the error with the rear axle GAWR values.

4/1/24 - Airstream begins investigation.

4/5/2024 - The Safety Committee reviews all known data and determines a recall is warranted. Airstream is unaware of any warranty or injury claims due to this non-compliance.

Description of Remedy :

Description of Remedy Program : Corrected labels will be sent to affected customers and dealers for installation. This will be done at no cost to the owner. Reimbursement will follow the general reimbursement policy that is on file with NHTSA.

How Remedy Component Differs from Recalled Component : The label will be printed with the correct rear axle GAWR values.

Identify How/When Recall Condition was Corrected in Production : The issue was corrected on April 1, 2024.

Recall Schedule :

Description of Recall Schedule : Airstream will send dealer and owner notification letters once approved by NHTSA.

Planned Dealer Notification Date : JUN 04, 2024 - JUN 04, 2024

Planned Owner Notification Date : JUN 04, 2024 - JUN 04, 2024

* NR - Not Reported