

# Part 573 Safety Recall Report

# 24V-351

**Manufacturer Name :** Forest River, Inc.**Submission Date :** MAY 17, 2024**NHTSA Recall No. :** 24V-351**Manufacturer Recall No. :** 34-1780**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

**Population :**

Number of potentially involved : 318

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2024-2024 Forest River Inc. Solera Class C Motorhomes

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Scope of vehicles built between 11/1/2023 when the manufacturing plant changed the routing of the LP line and 5/2/2024 when a steel P Clamp was added to secure the line.

2024	SOLERA	DSC22NC	8
2024	SOLERA	DSC23SC	2
Grand Total			10

Production Dates : NOV 01, 2023 - APR 30, 2024

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2024-2025 Forest River Inc. Forester Class C Motorhomes

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : 2024

FORESTER

FRC2151SLEC

8

2024

FORESTER

FRC2151SLEF

1

2024

FORESTER

FRC2251SLEC

16

2024

FORESTER

FRC2351LEC

43

2024

FORESTER

FRC2351LEMC

21

2025

FORESTER

FRC2151SLEC

4

2025

FORESTER

FRC2151SLEF

2

2025

FORESTER

FRC2351LEMC

1

Grand Total

96

Scope of vehicles built between 11/1/2023 when the manufacturing plant changed the routing of the LP line and 5/2/2024 when a steel P Clamp was added to secure the line.

Production Dates : NOV 01, 2023 - APR 30, 2024

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 3 : 2024-2025 Forest River Inc. Sunseeker Class C Motorhomes

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Scope of vehicles built between 11/1/2023 when the manufacturing plant changed the routing of the LP line and 5/2/2024 when a steel P Clamp was added to secure the line.

2024	SUNSEEKER	SSC2150SLEC	14	
2024	SUNSEEKER	SSC2150SLEF	2	
2024	SUNSEEKER	SSC2250SLEC	19	
2024	SUNSEEKER	SSC2250SLEF	1	
2024	SUNSEEKER	SSC2350LEC	37	
2024	SUNSEEKER	SSC2350LEF	2	
2024	SUNSEEKER	SSC2350LEMC	18	
2025	SUNSEEKER	SSC2150SLEFRB		75
2025	SUNSEEKER	SSC2250SLEC	2	
2025	SUNSEEKER	SSC2350LEC	5	
2025	SUNSEEKER	SSC2350LEF	9	
2025	SUNSEEKER	SSC2350LEMC	3	
2025	SUNSEEKER	SSC2350LEMCRB		25
Grand Total			212	

Production Dates : NOV 01, 2023 - APR 30, 2024

VIN Range 1 : Begin : NR End : NR

Not sequential

## Description of Defect :

Description of the Defect : The LP line may not be secured properly.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the LP Line is not secured properly, this can lead to a damaged LP Line potentially leading to a leak which may result in a fire, property damage or personal injury.

Description of the Cause : Manufacturing Error

Identification of Any Warning : The LP line would be visibly hanging below the body of the unit near the rear that can Occur : tires.

## Involved Components :

Component Name 1 : LP Line

Component Description : LP Line

Component Part Number : N/A

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

On May 2, 2024, Corporate PDI noticed the LP line sagging near the rear tire during an inspection. The zip tie was missing allowing the LP line to droop in front of the rear wheels. On that same day, the plant added a steel P Clamp to secure the line.

On May 10, 2024, the manufacturing plant contacted Forest Rivers Office of Corporate Compliance ("OCC"). OCC began researching the same day to determine if vehicles outside of Forest River control were affected.

On May 15, 2024, Forest Rivers Office of Corporate Compliance ("OCC") determined the scope of vehicles affected.

On May 17, 2024, Forest Rivers Corporate Recall Committee voted to recall.

## Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to install a P Clamp which will secure the LP line properly.

What is the Forest River Customer Service Phone Number? (574)  
206-7600

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.  
Please send the service invoice to the following address:

Forest River Class C  
Forest River, Inc.  
Attn: WARRANTY MANAGER  
55135 CR 1  
Elkhart, IN 46514

How Remedy Component Differs from Recalled Component : Affected Component - LP Line  
Replacement Component - Steel P Clamp

The LP Line will now be secured properly with a steel P Clamp. This is not a component failure, it is an installation error during manufacturing.

Identify How/When Recall Condition was Corrected in Production : On 5/2/2024 a steel P clamp was added to secure the line on all units.

## Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : JUN 26, 2024 - JUN 26, 2024

Planned Owner Notification Date : JUN 26, 2024 - JUN 26, 2024

\* NR - Not Reported