

Part 573 Safety Recall Report

24V-360

Manufacturer Name : Diamond Coach Corporation

Submission Date : MAY 22, 2024

NHTSA Recall No. : 24V-360

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Diamond Coach Corporation

Address : 2305 US Highway 59

Oswego KS 67356

Company phone : 620-795-2191

Population :

Number of potentially involved : 10

Estimated percentage with defect : 15 %

Vehicle Alterer Information :

Vehicle 1 : 2023-2024 Diamond Coach VIP 2200

Descriptive Information : The recall population was determined by identifying the total number of GO-ES Spacesaver Foldaway Seats manufactured by Freedman Seating Company, part numbers 88335, 89316, 102860, and 102861, that were purchased and installed by Diamond Coach from December 11, 2023 through January 31, 2024.

Production Dates : DEC 11, 2023 - JAN 31, 2024

Description of Defect :

Description of the Defect : See NHTSA Recall #24E026 -Freedman Seating Company (FSC) has decided that a defect which relates to motor vehicle safety exists in certain GO-ES Spacesaver Foldaway Seats manufactured between December 11, 2023 and January 31, 2024. The seat back cushion may become disengaged from the dump mechanism when there is a high load applied to the shoulder portion of the seat belt. The seat back may not support an FMVSS 210 shoulder belt load when it is in the fully reclined position.

FMVSS 1 : 210 - Seat belt assembly anchorages

FMVSS 2 : NR

Description of the Safety Risk : If the seat back recliner mechanism is not fully engaged the seat back could release when a substantial load is applied to the shoulder belt potentially increasing the risk of injury to the seat occupant during a vehicle crash.

Description of the Cause : Incorrect welding process and use of welding fixtures.

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name : GO-ES Spacesaver Foldaway Seat

Component Description : Freedman Foldaway Seat

Component Part Number : 88335,89316,102860, & 102861

Supplier Identification :

Component Manufacturer

Name : Freedman Seating Company

Address : 4545 W. Augusta Blvd.

Chicago Illinois 60651

Country : United States

Chronology :

Freedman Seating Company initiated NHTSA recall # 24E026 May 2024

Description of Remedy :

Description of Remedy Program : Diamond Coach will notify the owners of the 10 VIP 2200 vehicles that had the suspect GO-ES Spacesaver Foldaway Seats installed in them and forward the Seat Inspection & Repair Procedure provided by Freedman. Freedman will reimburse the cost of any repairs relating to this recall at no cost to the vehicle manufacturer, dealer, or owner. The remedy will consist of a visual inspection of the recliner mechanism lever when the seat back is in the upright and reclined positions. Instructions have been developed for this inspection and in how to determine if the seat requires rework, instructions have been provided on how to do this. Seat disassembly nor no new parts are required.

How Remedy Component Differs from Recalled Component : The position of the recliner mechanism handle for the remedy component will be in the same position when the seat back is in the upright and reclined positions.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : JUN 03, 2024 - JUN 27, 2024

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported