

# Part 573 Safety Recall Report

# 24V-435

**Manufacturer Name :** Jayco, Inc.

**Submission Date :** JUN 13, 2024

**NHTSA Recall No. :** 24V-435

**Manufacturer Recall No. :** 9901609



## Manufacturer Information :

**Manufacturer Name :** Jayco, Inc.

**Address :** 903 South Main Street

PO Box 460 Middlebury IN 46540

**Company phone :** 800-283-8267

## Population :

**Number of potentially involved :** 24

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2024-2024 Jayco Jay Feather Travel Trailer

**Vehicle Type :** TRAILERS

**Body Style :** OTHER

**Power Train :** NR

**Descriptive Information :** Jayco Inc. determined the population from production records.

**Production Dates :** MAR 25, 2024 - MAY 14, 2024

**VIN Range 1 : Begin :** 1UJBB0BT2R1JR0112 **End :** 1UJBB0BT4R1JR0144  Not sequential

## Description of Noncompliance :

**Description of the Noncompliance :** Certain 2024 Jay Feather TT model (JR) 29QBH had incorrect 14" spare tires installed in production instead of the correct 15" spare tires. The installed spare tire differs in size and required inflation pressure from the information on the tire placard. These trailers fail to comply with the requirements of FMVSS number 110, "Tire selection and rims and motor home/recreation vehicle trailer load carrying capacity information for motor vehicles with a GVWR less than 4,536 kilograms (10,000 pounds) or less".

**FMVSS 1 :** 110 - Tire selection and rims

**FMVSS 2 :** NR

**Description of the Safety Risk :** The owner, referencing the tire placard label, may incorrectly inflate the spare tire, increasing the risk of a crash.

**Description of the Cause :** Production assembly error: 14" spare tires installed in Jayco Inc. production instead of the correct 15" spare tires.

**Identification of Any Warning that can Occur :** None

## Involved Components :

Component Name 1 : TIRE, SPARE 15" E-RNG RAINIER ST225/75R15E

Component Description : TIRE, SPARE 15" E-RANGE RAINIER ST225/75R15E 6 LUG 15.00X6.00 K 6-5.5 SS  
BLACK SPOKE WITH TR600 VALVE.

Component Part Number : 2056467

## Supplier Identification :

### Component Manufacturer

Name : TREDIT TIRE & WHEEL CO., INC

Address : 3305 CHARLOTTE AVE  
Elkhart Indiana 46517

Country : United States

## Chronology :

On May 21, 2024 production emailed Jayco compliance that certain Jayco Jayfeather units were built with the incorrect spare tire installed. Upon investigation found that, we were in fact installing a 14" spare tire instead of a 15" on the Jayfeather (JR) 29QBH models.

On May 28, 2024 the Warranty Incident Review Committee (WIRC) discussed the incident and determined it should be elevated to CPAC.

On June 5, 2024 the Corrective and Preventive Action Committee (CPAC) met to discuss this incident and elevated it to the Safety Steering Committee.

On June 7, 2024 the Safety Steering Committee voted in favor of proceeding with a noncompliance recall for failing to comply with FMVSS number 110, "Tire Selection and Rims".

## Description of Remedy :

Description of Remedy Program : Jayco Dealers will replace the incorrect 14" spare tire with the correct 15" spare tire. Repairs made prior to the recall will be reimbursed in accordance with our Recall Reimbursement Plan on file with NHTSA. There are no warranty claims or complaints associated with this recall. Jayco Inc. will be reporting the quarterly completion rates to NHTSA.

How Remedy Component Differs from Recalled Component : Remedied units will have the correct 15" spare tire.

Identify How/When Recall Condition was Corrected in Production : The Jay feather model (JR) 29QBH built after May 21, 2024 will have the correct 15" spare tire installed in production.

**Recall Schedule :**

Description of Recall Schedule : Jayco will notify its dealers and affected retail owners.

Planned Dealer Notification Date : JUL 19, 2024 - JUL 19, 2024

Planned Owner Notification Date : JUL 19, 2024 - JUL 19, 2024

\* NR - Not Reported