

# Part 573 Safety Recall Report

## 24V-772

**Manufacturer Name :** BMW of North America, LLC**Submission Date :** OCT 17, 2024**NHTSA Recall No. :** 24V-772**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : BMW of North America, LLC

Address : P.O. Box 1227

Westwood NJ 07675-1227

Company phone : 18005257417

**Population :**

Number of potentially involved : 7

Estimated percentage with defect : 1 %

**Vehicle Information :**

Vehicle 1 : 2025-2025 BMW X3 (X3 xDrive30i, X3 M50i)

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

**Descriptive Information :** Approximately 7 vehicles have been manufactured with a front passenger air bag that may have been damaged during transport/handling between the Tier 2 and Tier 1 suppliers.

**Basis for recall population determination:** Vehicle assembly information and supplier production records were used to determine the specific dates of potentially affected vehicles.

**Recall component difference to non-recall component:** The front passenger air bag may have been damaged during transport/handling between the Tier 2 and Tier 1 suppliers.

Production Dates : JUL 16, 2024 - AUG 19, 2024

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** This safety recall involves the front passenger air bag. During transport/handling between the Tier 2 and Tier 1 suppliers, the air bag fabric may have been damaged.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** In a crash in which deployment of the front passenger air bag is warranted, the air bag may not inflate appropriately. This could result in insufficient

restraint capability to the front passenger, which could increase the risk of injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

## Involved Components :

Component Name 1 : Front Passenger Air Bag

Component Description : Front Passenger Air Bag

Component Part Number : 5A1E2D9

## Supplier Identification :

### Component Manufacturer

Name : Draexlmaier

Address : 1751 E. Main St.  
Duncan South Carolina 29334

Country : United States

## Chronology :

Please refer to BMW's September 25, 2024 Part 579 report assigned Foreign Recall ID 24F-220 by NHTSA.

Although initial information indicated that potentially affected vehicles for the US market were all contained, preliminary reviews suggested that a small number of potentially affected vehicles may have been released from the vehicle assembly plant.

In October, further reviews and analyses were conducted to determine which, if any, vehicles may have been potentially affected.

Vehicle assembly information and supplier production records were used to determine the specific dates of potentially affected vehicles.

As a result, BMW will be conducting a voluntary safety recall for these specific vehicles.

## Description of Remedy :

Description of Remedy Program : The front passenger air bag will be replaced.

Owners will be notified by First Class mail advising them of the recall and to schedule an appointment with an authorized BMW dealer to have the remedy performed for free. Although unlikely, owners who have had this remedy performed at their own expense prior to the recall notification, may be eligible for reimbursement according to BMW Group's reimbursement plan in accordance with 49 CFR 573.13 and 49 CFR 577.11.

How Remedy Component Differs from Recalled Component : Recalled Component: front passenger air bag – p/n: 5A1E2D9

Identify How/When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : Dealer notification is planned to begin and end on October 17, 2024.  
Owner notification is planned to begin and end on December 9, 2024.

Planned Dealer Notification Date : OCT 17, 2024 - OCT 17, 2024

Planned Owner Notification Date : DEC 09, 2024 - DEC 09, 2024

\* NR - Not Reported